

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008076/EQF3E2

Date: 25/08/2021

REFERENCE

Insured/Claimant:	NG XUE LI, SHERLENE	Policy No:	2000000418		
Date of Loss:	29/07/2021	Nature of Claim:	OD	Claim No:	7267556476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4117Y	Engine No:	G4FGKH739336
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416ML5059975
Reg. Date:	03/01/2020 (Man. Year: 2019)	Odometer:	48709 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$83,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,986.60	6,070.60	916.00	13.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,010.00	4,690.00	320.00	6.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,996.60	10,760.60	1,236.00	10.30
+ GST 7.00/7.00% (S\$)	839.76	753.24	86.52	10.30
Nett Amount (S\$)	12,836.36	11,513.84	1,322.52	10.30

INSPECTION

Date of Assignment:	30/07/2021	
Date Inspected:	30/07/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
2	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
3	1		*BODY PNL SEALANT	Necessary	60.00 FS	*60.00 FS
4	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
5	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
6	1		*K3 BOOT LIP SPOILER	Broken	211.00 FS	*211.00 FS
7	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
8	1		*HINGE ASSY-TRUNK LID, LH	Bent	97.00 FL	*97.00 FL
9	1		*HINGE ASSY-TRUNK LID, RH	Bent	97.00 FL	*97.00 FL
10	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
11	1		*TRIM ASSY-TRUNK LID	Crushed	202.00 FL	*202.00 FL
12	1		*LATCH ASSY-TRUNK LID	Cut	112.00 FL	*112.00 FL
13	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
14	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
15	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
16	1		*LAMP ASSY-CENTER GARNISH	Broken	690.00 FL	*690.00 FL
17	1		*LAMP ASSY-REAR COMB INSIDE, LH	Cut	608.00 FL	*608.00 FL
18	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cut	608.00 FL	*608.00 FL
19	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Cut	675.00 FL	*675.00 FL
20	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
21	1		*TRIM ASSY-RR TRANSVERSE	Crushed	41.00 FL	*41.00 FL
22	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	211.00 FL	*- FL
23	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
24	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
25	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	19.00 FL	*- FL
26	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	19.00 FL	*19.00 FL
27	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
28	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
29	1		*EXTN WIRING ASSY-BWS	Broken	207.00 FL	*207.00 FL
30	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
31	1		*STAY-RR BUMPER, LH	Not Necessary	65.00 FL	*- FL
32	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
33	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
34	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
35	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
36	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	12.00 FL	*- FL
37	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
38	1		*COVER-RR BUMPER UNDER, RH	Not Necessary	33.00 FL	*- FL
39	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
40	1		*COVER-RR BUMPER UNDER, LH	Not Necessary	33.00 FL	*- FL
41	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 FL	*675.00 FL
42	5		*FASTENER (Supplementary)	Necessary	5.00 FL	*5.00 FL
43	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,583.00	7,493.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,596.40	1,422.40
Total Parts (\$\$)	6,986.60	6,070.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, RR END PNL, BOOTLID & BOOTLID SPOILER. REPAIR RR FLR PNL, LHR FENDER & RHR FENDER	New	2,400.00	2,080.00
2	RESPRAY RR BUMPER, RR END PNL, BOOTLID, BOOTLID SPOILER, LHR FENDER & RHR FENDER	New	2,100.00	2,100.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, CARPET & TRIM	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	REMOVE & REFIT REVERSE SENSOR	New	80.00	80.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
Gross Labour Cost (\$)			5,010.00	4,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >