

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING	Ollassis iii	/NG XUE LI, SHERLENE (HUANG XUEL SMR4117Y / 03/01/202	
SINGAPORE 079120 Contact No 64191000	Make/Model Colour/Trim	KIA/CERATO 1.6 A EX G333 KLG STEEL GREY / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	na ne nijelekteri sirili. Na prostorila are tyakir.	WIP No			
AX00000	Credit	29/07/2021/ 16:57		261 / Edwin Caina		37006			
ANUUUUU	Credit	Description of Goo			Qty	Unit Price	Disc%	An	nount
PNT88000 RENEW RR	BUMPER ,		LID & BOOTL	\$0 ID SPOILER 5 X 400				2080	2400.00
PNT98000 RESPRAY F	(PLK PNL RR BUMPER	, RR END PNL , BO	I LINDER	1 .	350				2100.00
PNT88000 REMOVE &		OTLID COMPONENT							120.00
PNT88000		FLR BOARD , CARPE	T & TRIM	(photo)					30.00
54900099 CHECK WIR 10028901	RING ELEC	TRICAL SYSTEM	Q1	ima')			120.00
TO CARRY SUNDRY		NOSTIC CHECK ON EL		NTROL SYSTEM CL		,			50.0
PNT88000		PLATE WITH CASING	BT						80.0
SUNDRY SUPPLY RE		VERSE SENSOR						8	220.0
SUNDRY		ION ON AFFECTED AR	EAS						40.0
SUNDRY SUPPLY BO	DY PNL SI	EALANT							60.0
SUNDRY SUPPLY C&	C BADGE								40.0 20.0
SUNDRY Sundries K3 BOOT L	ID SDOIL	FR / OR			1.00	211 00	00.00		211.0
PANEL ASS HINGE ASS HINGE ASS	Y-TRUNK Y-TRUNK Y-TRUNK	LID $/$ 00 $0\overline{1}$ LID, LH $/$ $0\overline{1}$ 0	,		1.00 1.00 1.00	1297.00 97.00 97.00	20.00 20.00 20.00	111	1037.6 77.6 77.6
Confirm & a		OPNG / CRY			1.00	100.00	20.00		80.0
			the Repairer To resurvey be To display dan	onsultants hence notify of the following: efore/after spray painting naged part(s) during resurvey re subject to confirmation					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other renair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.

Third party survey is on a "Without Prejudice" basis



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Cust No/Name

Chassis No

Date In/Mileage

Reg No/Reg Date SMR4117Y

Owner Name & Vehicle Info

KNAF3416ML5059975

/ 03/01/202

48709

Co Reg No : 199405410K Invoice Name & Address

> AIG Asia Pacific Insurance Pte. MOTOR CLAIM DEPARTMENT

78 SHENTON WAY #09-16 ATC DUTI DING

ES	TI	M	A	TE	

GST Reg No : MR-8500111-X

/NG XUE LI, SHERLENE (HUANG XUEL

AIG BUILDING	Fundana Na	G4FGKH739336 KIA/CERATO 1.6 A EX G333				
SINGAPORE 079120 Contact No 64191000	Engine No					
	Make/Model	and the state of t			BLACK	
	Colour/Trim	KLG STEEL G	REY /	WK SATUR	BLACK	
					r produce - produce such	
Account No Terms Date/Time Printed CSE	Operator		WIP No			
AX00000 Credit 29/07/2021/ 16:57 BLE	261 / Edwin Ca	aina	37006			
Description of Goods / Services	The second section of the second seco	Qty	Unit Price		Amount	
M TRIM ASSY-TRUNK LID / CRU		1.00	202.00		161.6	
M LATCH ASSY-TRUNK LID / CMT		1.00	112.00	20.00	89.6	
M STRIKER ASSY-TRUNK LID 🗶 📉		1.00	40.00	20.00	32.0	
M LOGO ASSY-KIA SUB - nec		1.00	32.00	20.00	25.0	
M EMPLEM_CEDATO - APC		1.00	28.00	20.00	22.4	
A LAND ACCY CENTED CADNICH - PK		1.00		20.00	552.	
M LAMP ASSY-REAR COMB INSIDE, LH CUT		1.00		20.00	486.	
A LAND ACCY DEAD COMP INCIDE DU		1.00		20.00	486.	
A LAMB ASSV DEAD COMP OUTSIDE IH		1.00		20.00	540.	
LAMP ASSY-REAR COMB OUTSIDE, RH / CMT		1.00		20.00	540.	
PANEL ASSY-BACK / PD		1.00		20.00	259.	
TRIM ASSY-RR TRANSVERSE / LCRY 657	TI FASS G	2.00		20.00	32.	
MAT ASSY-LUGGAGE COVERING	6	1 1.00		20.00	168.	
COVER-RR BUMPER / GR		11 (4.00)		20.00	520.	
COVED DD DIMDED IND	-	1.00		20.00	192.	
COVER-RE BUMPER FOG LAMP, LH		1.00		20.00	15.	
COVER-RR BUMPER FOG LAMP, RH		1.00		20.00	15.	
LAMP ASSY-SIDE T/SIGNAL, LH 2 7 MM		1.00		20.00	144.	
LAMP ASSY-SIDE T/SIGNAL RH		1.00	181.00	20.00	144	
EXTN WIRING ASSY-BWS ? - BR		1.00	207.00	20.00	165	
BEAM-RR BUMPER / BR		1.00	318.00	20.00	254	
STAY-RR BUMPER LH 14 TOP		1.00	65.00	20.00	52	
STAY-RR BUMPER RH		1.00	65.00	20.00	52	
BRACKET-RR BEAM UPR MTG, LH		1.00	9.00	20.00	7.	
BRACKET-RR BEAM UPR MTG,RH ? X NP		1.00	9.00	20.00	7	
BRACKET-RR BEAM LWR, CTR ?		1.00		20.00	4.	
BRACKET-RR REAM I WR MTG		2.00		20.00	9.	
ANTENNA ASSY-SMARTKEY 1		1.00		20.00	36.	
COVER-RR BUMPER UNDER, RH		1.00		20.00	26.	
1 BRACKET ASSY-RR BPR SIDE UPR,L		1.00		20.00	20.	
A COVED DD DUMDED UNDED LIL A		1.00		20.00	26.	
(4	eve CLKK)			2X		
SURVEYOR NAME :				- 1		
SURVETURINAIME.		7		9		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also shows a started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or cheque. You must also shows a started and needed for repairs of renew. cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DATE: OP- NA

Authorized signatory and company stamp

11,976.60

12,814.96

838.36

Nett

11976.60

Total Payable

7% GST on