

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |                                    |                 |       |                          |  |
|---|--|------------------------------------|-----------------|-------|--------------------------|--|
|   | AIG ASIA PACIFIC   | INSURANCE PTE LTD                  |                 | Ref:  | CS3/AIG21007133/Gqf3n2-1 |  |
|   | 78 SHENTON WAY<br>AIG BUILDING<br>SINGAPORE 0791   |                                    |                 | Date: | 19/08/2021               |  |
|   |  |                                    |                 | Code: | AIG                      |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |                                    |                 |       |                          |  |
|   | Insured Veh.   | SLN 2912P                          | Veh. Inspected  |       | SGT 3346U                |  |
|   | Policy No.   | 2070036736                         | Coverage (\$)   |       | 0.00                     |  |
|   | Claim No.  | 0012328960SG                       | Excess (\$)     |       | 0.00                     |  |
|   | Assign From  | SALIHA SYED YUSOF                  | Assign Date     |       | 30/07/2021               |  |
| 2. Vehicle Particulars & Condition                                |  |                                    |                 |       |                          |  |
|   | Make & Model   | TOYOTA ALTIS 1.6                   | c.c             |       | 1598                     |  |
|   | Engine No.   | HIDDEN                             | Year of Reg.    |       | 2010                     |  |
|   | Chassis No.  | MR053ZEE106177402                  | Colour          |       | BLACK                    |  |
|   | Odometer   | 177483 KM                          | Steering        |       | IN ORDER                 |  |
|   | Brakes   | IN ORDER                           | Modification    |       | STANDARD ALLOY RIM       |  |
|   | General  | GOOD                               |                 |       |                          |  |
| 3. Conditions of Tyres  |  |                                    |                 |       |                          |  |
|   |  | Size                               | Make            |       | Balance                  |  |
|   | R/H Front Tyre   | 205/65 R15                         | HABILEAD        |       | 6 mm                     |  |
|   | L/H Front Tyre   | 205/65 R15                         | HABILEAD        |       | 6 mm                     |  |
|   | R/H Rear Tyre  | 205/65 R15                         | HABILEAD        |       | 6 mm                     |  |
|   | L/H Rear Tyre  | 205/65 R15                         | HABILEAD        |       | 6 mm                     |  |
| 4.  | Description of Damages   |                                    |                 |       |                          |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                                    |                 |       |                          |  |
|   | DAMAGES SEE DETAILS.   |                                    |                 |       |                          |  |
| 5.  | General Information  |                                    |                 |       |                          |  |
|   | Accident Date  | 26/06/2021                         | Inspection Date | 9     | 29/06/2021               |  |
|   | Survey held at   | held at CHENG CHUAN MOTOR SERVICES |                 |       |                          |  |
|   |  | BLK 1068 EUNOS AVE 5<br>#01-215    |                 |       |                          |  |
|   |  | SINGAPORE 409747                   |                 |       |                          |  |
| 5a.   |  |                                    |                 |       |                          |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                    |                 |       |                          |  |
| 5b.   | Estimate Days of Repair  |                                    |                 |       |                          |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days   |                                    |                 |       |                          |  |
|   |  |                                    |                 |       |                          |  |