

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008086/EQCE2**Date:** 13/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00015862100		
Claimant Vehicle No :	XD3184C	Insured Vehicle No :	YN2055J		
Date of Loss:	25/07/2021	Nature of Claim:	TP	Claim No:	SNM21D204120/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD3184C	Engine No:	6M70428765
Make & Model:	MITSUBISHI FV51JJD4RDEA, 12.9 D (M)	Chassis No:	FV51JJA00419
Reg. Date:	19/12/2008 (Man. Year: 2008)	Odometer:	806449 km
Colour:	Blue		
Engine Capacity:	12882 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	ANNAITE 4 mm	Rear Left Side:	ANNAITE 4 mm
Front Right Side:	ANNAITE 4 mm	Rear Right Side:	ANNAITE 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	65,000.00	36,000.00	29,000.00	44.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	65,000.00	36,000.00	29,000.00	44.62
+ GST 8.00/8.00% (\$\$)	5,200.00	2,880.00	2,320.00	44.62
Nett Amount (\$\$)	70,200.00	38,880.00	31,320.00	44.62

INSPECTION

Date of Assignment:	30/07/2021		
Date Inspected:	02/08/2021	Inspected At:	Samwoh Corporation Pte Ltd (HQ) 25E Sungei Kadut Street 1 Singapore 729333
Estimated Period of Repair:	14.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Mar 2023)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD3184C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUPPLY AND INSTALL ONE NEW SET OF SS180M TMA	New	65,000.00	36,000.00
Gross Labour Cost (\$\$)			65,000.00	36,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >