

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121008088/KTF3N2**Date:** 20/08/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHB7724T **Insured Vehicle No :** GBG7629E

Date of Loss: 29/07/2021 Nature of Claim: TP Claim No: CDMCG21001397

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHB7724T**

Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR2C27772

Reg. Date: 18/06/2019 (Man. Year: 2018) Chassis No: JTDKB3FU303081296

Colour: Metallic Pearl White/Red Odometer: 167146 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Sailun 9 mm Rear Left Side: Sailun 8 mm

Front Right Side: Sailun 9 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,208.17	5,700.52	3,507.65	38.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,670.00	3,430.00	67.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,308.17	7,370.52	6,937.65	48.49
+ GST 7.00/7.00% (S\$)	1,001.57	515.94	485.63	48.49
Nett Amount (S\$)	15,309.74	7,886.46	7,423.28	48.49

INSPECTION

Date of Assignment: 30/07/2021

Date Inspected: 02/08/2021 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Aug 2021)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7724T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD,REAR BUMPER CENTER	Bent	576.30 FL	*576.30 FL
4	1		*SEAL REAR BUMPER SIDE,LH	Serviceable	88.50 FL	*- FL
5	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	116.50 FL	*- FL
6	1		*PANEL SUB-ASSY,BODY LOWER BACK	Bent	650.30 FL	*650.30 FL
7	1		*FILLER,REAR BUMPER EXTENSION,LH	Repair	123.70 FL	*- FL
8	1		*FILLER,REAR BUMPER EXTENSION,RH	Repair	123.70 FL	*- FL
9	1		*LENS AND BODY,REAR LAMP,LH	Cracked	502.00 FL	*502.00 FL
10	1		*LENS & BODY,REAR COMBINATION LAMP,LH	Serviceable	443.30 FL	*- FL
11	1		*LENS AND BODY,REAR LAMP,RH	Serviceable	502.00 FL	*- FL
12	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Serviceable	451.80 FL	*- FL
13	1		*MOULDING SUB-ASSY,ROOF DRIP SIDE FINISH,REAR LH	Serviceable	54.40 FL	*- FL
14	1		*MOULDING SUB-ASSY,ROOF DRIP SIDE FINISH,REAR RH	Serviceable	54.40 FL	*- FL
15	1		*PANEL SUB-ASSY,BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
16	1		*STAY ASSY,BACK DOOR,LH	Serviceable	242.50 FL	*- FL
17	1		*STAY ASSY,BACK DOOR,RH	Serviceable	242.50 FL	*- FL
18	1		*HINGE ASSY,BACK DOOR,LH	Distorted	61.00 FL	*61.00 FL
19	1		*HINGE ASSY,BACK DOOR,RH	Distorted	61.00 FL	*61.00 FL
20	1		*SPOILER SUB-ASSY,REAR	Cracked	1,575.40 FL	*1,575.40 FL
21	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Warped	925.60 FL	*925.60 FL
22	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	*47.90 FL
23	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME,NO.2	Necessary	54.60 FL	*54.60 FL
24	1		*PLATE,BACK DOOR NAME,NO.1	Necessary	54.60 FL	*54.60 FL
25	1		*COVER,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
26	1		*COVER,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
27	1		*COVER,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
28	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
29	1		*REAR BUMPER SIDE CLIP	Not Necessary	60.00 FS	*- FS
30	1		*BOOTLID STICKER TRANSCAB	Necessary	100.00 FS	*30.00 FS
31	1		*BOOTLID STICKER 65553333	Necessary	100.00 FS	*30.00 FS
32	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
33	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*50.00 FS
34	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
35	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
36	2		*SET TAILLAMP CLIP	Not Necessary	100.00 FS	*- FS
37	1		*ANTENNA ELECTRICAL KEY	Dented	72.00 FL	*72.00 FL
38	1		*MOULDING SUB-ASSY,ROOF TOP	Mtg Broken	656.90 FL	*656.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,770.90	7,490.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,562.73	1,790.18
Total Parts (\$\$)	9,208.17	5,700.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,600.00	600.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	880.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >