

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008089/KGS3Q2**Date:** 11/01/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800110107
<b>Claimant Vehicle No :</b>	SME1830J	<b>Insured Vehicle No :</b>	SJG8809B
Date of Loss:	30/07/2021	Nature of Claim:	TP
		Claim No:	1167523830SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SME1830J</b>	Engine No:	4J11YP4583
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0401965
Reg. Date:	21/09/2018 (Man. Year: 2018)	Odometer:	52200 km
Colour:	Metallic Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,446.40	7,011.60	2,434.80	25.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,675.00	2,180.00	495.00	18.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,121.40</b>	<b>9,191.60</b>	<b>2,929.80</b>	<b>24.17</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,350.00</b>		
<b>(S\$)</b>	12,121.40	7,350.00	4,771.40	39.36
<b>+ GST 7.00/7.00% (S\$)</b>	848.50	514.50	334.00	39.36
<b>Nett Amount (S\$)</b>	<b>12,969.90</b>	<b>7,864.50</b>	<b>5,105.40</b>	<b>39.36</b>
<b>+ Car Rental (14.0 x S\$120.00/day) (S\$)</b>		1,680.00		
<b>Nett Liability (S\$)</b>		<b>9,544.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,500.00</b>		

**INSPECTION**

Date of Assignment:	30/07/2021	
Date Inspected:	02/08/2021	Inspected At: S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	9.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	970.00 FL	*970.00 FL
2	1		*TAILGATE CENTRE MOULDING	Mtg Cracked	466.00 FL	*466.00 FL
3	1		*TAILGATE CENTRE MOULDING EMBLEM	Serviceable	39.00 FL	*- FL
4	1		*TAILGATE BADGE OUTLANDER	Necessary	86.00 FL	*86.00 FL
5	1		*TAILGATE BADGE MIVEC TECHNOLOGY	Necessary	75.00 FL	*75.00 FL
6	1		*TAILGATE BADGE C&C	Necessary	65.00 FL	*65.00 FL
7	1		*TAILGATE WEATHERSTRIP	Distorted / Cut	192.00 FL	*192.00 FL
8	1		*TAILGATE INNER TRIM BOARD	Buckled	360.00 FL	*312.00 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	28.00 FL	*28.00 FL
10	1		*TAILGATE INNER LOCK	Dented	428.00 FL	*428.00 FL
11	1		*RH TAILGATE INNER TAIL LAMP	Cut	397.00 FL	*397.00 FL
12	1		*LH TAILGATE INNER TAIL LAMP	Mtg Cracked	397.00 FL	*397.00 FL
13	1		*RH OUTER TAIL LAMP	Serviceable	563.00 FL	*- FL
14	1		*LH OUTER TAIL LAMP	Serviceable	563.00 FL	*- FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FL	*160.00 FL
16	1		*REAR BUMPER	Bent	873.00 FL	*873.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
18	1		*REAR BUMPER CENTRE LOWER MOULDING	Cracked	209.00 FL	*209.00 FL
19	1		*RH REAR BUMPER RETAINER	Distorted	24.00 FL	*24.00 FL
20	1		*LH REAR BUMPER RETAINER	Distorted	24.00 FL	*24.00 FL
21	1		*RH REAR BUMPER BRACKET	Bent	71.00 FL	*71.00 FL
22	1		*LH REAR BUMPER BRACKET	Bent	71.00 FL	*71.00 FL
23	1		*RH REAR BUMPER FOG LAMP	Serviceable	120.00 FL	*- FL
24	1		*LH REAR BUMPER FOG LAMP	Serviceable	120.00 FL	*- FL
25	1		*REAR END PANEL	Bent	299.00 FL	*299.00 FL
26	1		*RH REAR END CORNER PANEL	Repair	188.00 FL	*- FL
27	1		*LH REAR END CORNER PANEL	Repair	188.00 FL	*- FL
28	1		*REAR END PANEL TOP TRIM	Distorted	111.00 FL	*111.00 FL
29	1		*REAR FLOOR PANEL	Repair	743.00 FL	*- FL
30	1		*REAR FLOOR TOP BOARD	Cracked	266.00 FL	*266.00 FL
31	1		*REAR EXHAUST MUFFLER	Bent	548.00 FL	*548.00 FL
32	1		*REAR BUMPER SIDE GARNISH LH	Dented	98.00 FL	*98.00 FL
33	1		*TAILGATE OPEN & CLOSED SWITCH	Dented	156.00 FL	*156.00 FL
34	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
35	1		*REAR WINDSCREEN INNER RUBBER SEAL	Necessary	28.00 FS	*28.00 FS
36	1		*SET REAR PARKING SENSOR	Dented	280.00 FS	*200.00 FS
37	1		*REAR PARKING CAMERA	Cracked	380.00 FS	*380.00 FS
38	1		*SET REAR BUMPER SIDE LOWER SPOILER	Buckled / Cracked	636.00 FS	*636.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,340.00</b>	<b>7,648.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	893.60	636.40
<b>Total Parts (\$\$)</b>	<b>9,446.40</b>	<b>7,011.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST	New	120.00	120.00
2	TO REMOVE REAR DAMAGED PARTS TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL AND CUT OUT BODY PANEL ,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL,REAR FLOOR PANEL ,REAR BODY PANEL,RH REAR FENDER ,LH REAR FENDER ,TO STRAIGHTEN OUT REAR CHASSIS MEMBER ,TO REPLACE DAMAGED PARTS AND ADJUST REAR BODY AND TAILGATE ALIGNMENT	New	1,100.00	900.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	35.00	20.00
4	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	1,200.00	1,000.00
5	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	60.00
6	REAR SPARE TYRE FLOOR GUM	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,675.00</b>	<b>2,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >