

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21008090/EVCN2**Date:** 07/09/2021**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00126072100

**Claimant Vehicle  
No :** SML629U**Insured Vehicle  
No :** SGZ5246E

Date of Loss: 20/07/2021

Nature of Claim: TP

Claim  
No: SNM21D204036/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SML629U**

Make &amp; Model: HONDA JAZZ, 1.3 (A)

Engine No: L13B14101054

Reg. Date: 03/05/2019 (Man. Year: 2019)

Chassis No: JHMGK3850KS214074

Colour: Yellow

Odometer: 27955 km

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 175/65 R15

Rear Tyre Size: 175/65 R15

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,786.78	588.43	1,198.35	67.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	1,420.00	3,540.00	71.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,746.78</b>	<b>2,008.43</b>	<b>4,738.35</b>	<b>70.23</b>
<b>+ GST 7.00/7.00% (S\$)</b>	472.27	140.59	331.68	70.23
<b>Nett Amount (S\$)</b>	<b>7,219.05</b>	<b>2,149.02</b>	<b>5,070.03</b>	<b>70.23</b>

**INSPECTION**

Date of Assignment: 30/07/2021

Date Inspected: 03/08/2021 Inspected At:

Kah Motor Co Sdn Bhd (ALEXANDRA)  
255 ALEXANDRA ROAD  
Singapore -

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2021)
<b>Parts:</b>	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML629U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Dented	403.57 FS	*403.57 FS
2	1		*LOWER GRILLE ASSY,FR	Not Necessary	118.05 FS	*- FS
3	1		*GARNISH,L FR BUMPER	Cut	23.17 FS	*23.17 FS
4	1		*BEAM,COMP,FR BUMPER	Not Necessary	170.32 FS	*- FS
5	1		*BEAM UPPER,L FR BUMPER	Not Necessary	22.20 FS	*- FS
6	1		*SPACERR.FR BUMPER	Not Necessary	7.80 FS	*- FS
7	1		*SPACERL.FR BUMPER	Necessary	7.80 FS	*7.80 FS
8	1		*CLIP,BUMPER (19 Pcs)	Necessary	32.77 FS	*32.77 FS
9	1		*DUCT,L FR BUMPER SIDE	Not Necessary	10.12 FS	*- FS
10	1		*HEADLIGHT ASSY,L	Not Necessary	383.62 FS	*- FS
11	1		*BASE,FR GRILLE HOOK	Not Necessary	181.87 FS	*- FS
12	1		*MOLDING LOWER FR GRILLE	Not Necessary	119.10 FS	*- FS
13	1		*MOLDING UPPER FR GRILLE	Not Necessary	99.22 FS	*- FS
14	1		*EMBLEM H	Not Necessary	12.90 FS	*- FS
15	2		*NUTPUSH 3MM	Not Necessary	3.15 FS	*- FS
16	1		*BASE,FR LICENCE PLATE	Cut	39.15 FS	*39.15 FS
17	1		*NUMBER PLATE WITH CASING-L	Cut	45.00 FS	*45.00 FS
18	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
19	1		*GARNISH,L FR LOWER GRILLE	Cracked	6.97 FS	*6.97 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>1,786.78</b>
						<b>588.43</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	280.00	250.00
2	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	2,600.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P)	New	2,080.00	520.00
<b>Gross Labour Cost (\$)</b>			<b>4,960.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >