

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III21006746/BTF3E2-1

**Date:** 17/08/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0007747  
**Claimant Vehicle No :** SJH9273J **Insured Vehicle No :** SMY9277Z  
Date of Loss: 16/06/2021 Nature of Claim: TP Claim No: MFL2021D0002580

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH9273J**  
Make & Model: HONDA AIRWAVE, 1.5 (A) Engine No: L15A5159145  
Reg. Date: 28/08/2008 (Man. Year: 2008) Chassis No: GJ11207737  
Colour: Silver Odometer: 194469 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14  
Front Left Side: Michelin 5 mm Rear Left Side: Neuton 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Neuton 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,817.12	4,021.84	3,795.28	48.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,470.00	740.00	33.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,027.12</b>	<b>5,491.84</b>	<b>4,535.28</b>	<b>45.23</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,400.00</b>		
<b>(S\$)</b>	10,027.12	4,400.00	5,627.12	56.12
<b>+ GST 7.00/7.00% (S\$)</b>	701.90	308.00	393.90	56.12
<b>Nett Amount (S\$)</b>	<b>10,729.02</b>	<b>4,708.00</b>	<b>6,021.02</b>	<b>56.12</b>

### INSPECTION

Date of Assignment: 30/07/2021  
Date Inspected: 16/06/2021 Inspected At: Assure Auto (HQ)  
B14 AMK BLK B  
Singapore 569116  
Estimated Period of Repair: 6.0 days

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2021)
<b>Parts:</b>	M1-MPV	HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJH9273J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,550.80 FL	*1,141.30 FL
2	1		*TAILGATE WINDSCREEN MOULDING (4PCS)	Necessary	380.80 FL	*112.50 FL
3	1		*TAIL GATE TOP LOCK	Jammed	365.50 FL	*109.00 FL
4	1		*TAIL GATE WEATHERSTRIP	Torn	215.10 FL	*145.00 FL
5	1		*TAIL GATE OUTER MOULDING	Not Damaged	452.60 FL	*- FL
6	1		*TAIL GATE REFLECTOR	N/S Broken / O/S Reuse	571.00 FL	*285.50 FL
7	1		*TAL GATE OUTER PROTECTOR	Dented	415.30 FL	*415.30 FL
8	1		*TAIL GATE EMBLEM AIRWAVE	Necessary	65.50 FL	*65.50 FL
9	1		*TAIL GATE INNER TRIM	Broken	480.60 FL	*258.30 FL
10	1		*TAIL GATE WIPER MOTOR	Not Damaged	454.20 FL	*- FL
11	1		*REAR BUMPER	Dented	1,320.80 FL	*945.20 FL
12	2		*REAR BUMPER SIDE RETAINER	Broken	171.00 FL	*82.00 FL
13	1		*REAR TAIL LAMP	N/S Broken / O/S Reuse	704.40 FL	*352.20 FL
14	1		*REAR END PANEL	Dented	612.50 FL	*508.00 FL
15	1		*REAR END PANEL TOP GARNISH	Broken	275.80 FL	*130.00 FL
16	1		*REAR FLOOR PANEL TOP BOARD	Not Damaged	342.60 FL	*- FL
17	2		*REAR NUMBER PLATE LAMP	Not Damaged	136.40 FL	*- FL
18	1		*REAR FENDER INNER TRIM LH	Not Damaged	521.30 FL	*- FL
19	1		*REAR BUMPER TOP BEAM	Bent	185.20 FL	*90.00 FL
20	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	50.00 FS	*30.00 FS
21	1		*REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
22	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	2		*REAR TAIL LAMP CLIPS	Not Necessary	10.00 FS	*- FS
24	1		*REAR REVERSE SENSOR	Short Circuit	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,661.40</b>	<b>4,949.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,844.28	927.96

<b>Total Parts (S\$)</b>	<b>7,817.12</b>	<b>4,021.84</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	855.00	600.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	900.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	50.00	20.00
4	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	60.00
5	TRANSFER OF EXISTING TAILGATE MECHANISM TO NEW TAILGATE	New	90.00	70.00
6	CONDUCT WATER LEAK TEST FOR REAR PORTION ASSOCIATED REPAIR WORKS	New	45.00	0.00
7	WIRING AND BULB CHECKING	New	36.00	0.00
8	REMOVE AND REFIX TAILGATE REAR WINDSCREEN GLASS (2-MAN JOB)	New	157.50	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,210.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >