

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008091/EES3Q2
Date: 15/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLX7241G	Insured Vehicle No :	SLM6544Y
Date of Loss:	27/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7241G		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGHH692842
Reg. Date:	09/04/2018 (Man. Year: 2017)	Chassis No:	KNAFZ411MJ5762759
Colour:	Grey	Odometer:	42354 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Nexen 4 mm	Rear Left Side:	Nexen 4 mm
Front Right Side:	Nexen 4 mm	Rear Right Side:	Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,700.00	845.00	1,855.00	68.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	3,290.00	930.00	22.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,920.00	4,135.00	2,785.00	40.25
+ GST 7.00/7.00% (S\$)	484.40	289.45	194.95	40.25

Nett Amount (S\$)	7,404.40	4,424.45	2,979.95	40.25
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,073.90		

INSPECTION

Date of Assignment: 30/07/2021

Date Inspected: 22/09/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX7241G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*C&C EMBLEM	Necessary	50.00 FS	*50.00 FS
3	1		*NEW K3 BODYKIT	Repair	1,177.00 FS	*- FS
4	1		*COVER -RR BUMPER	Dented	688.00 FS	*688.00 FS
5	1		*COVER -RR BUMPER CTR	Not Necessary	315.00 FS	*- FS
6	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
7	2		*BRACKET -RR BEAM LWR MTG	Not Necessary	10.00 FS	*- FS
8	1		*BRACKET -RR BEAM LWR CTR	Not Necessary	5.00 FS	*- FS
9	1		*LOGO ASSY -KIA SUB	Necessary	37.00 FS	*37.00 FS
10	1		*EMBLEM -CERATO	Necessary	35.00 FS	*35.00 FS
11	1		*EMBLEM K3	Necessary	15.00 FS	*15.00 FS
					Total Parts (\$\$)	2,700.00
						845.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REAR BUMPER ,BODYKIT & AFFECTED AREA REPAIR ON BOOT LID	New	1,920.00	1,040.00
2	PAINT WORK ON REAR BUMPER ,BOOT LID & BODYKIT	New	1,650.00	1,650.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	150.00	120.00
4	TO APPLY SEALANT ON AFFECTED AREA	New	50.00	50.00
5	PERFORM RUST PREVENTION	New	50.00	30.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	120.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (S\$)			4,220.00	3,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >