LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008092/BQF3E2

27/10/2021 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001776106

Claimant Vehicle SKA576U Insured Vehicle No: YN9999P

No:

Date of Loss: 29/07/2021 Nature of Claim: TP Claim No: 260626

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA576U**

Make & Model: BMW X3 SDRIVE, 2.0 20I LED SR NAV (A) 21065206B48B20A Engine No: Reg. Date: 18/05/2018 (Man. Year: 2018) Chassis No: WBATR12010LC94190

Colour: Odometer: 52596 km Blue

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 245/50 R19 Rear Tyre Size: 245/50 R19 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|-----------------------------------|------------|------------|------------|--------|
| Parts | | 13,224.30 | 2,655.04 | 10,569.26 | 79.92 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 4,470.00 | 600.00 | 3,870.00 | 86.58 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 17,694.30 | 3,255.04 | 14,439.26 | 81.60 |
| | Approved Total (Overridden) (S\$) | | 2,600.00 | | |
| | (S\$) | 17,694.30 | 2,600.00 | 15,094.30 | 85.31 |
| | + GST 7.00/7.00% (S\$) | 1,238.60 | 182.00 | 1,056.60 | 85.31 |
| | Nett Amount (S\$) | 18,932.90 | 2,782.00 | 16,150.90 | 85.31 |

INSPECTION

Date Inspected:

Date of Assignment: 30/07/2021

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan Manager: SHIAU CHAN

02/08/2021 Inspected At:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Oct 2021)

Parts: M1-SUV BMW X3 SDRIVE 2.0 20I LED SR NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA576U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--|-------------|--|-------------------|-------------|--------------|
| 1 | 1 | | *LH SIDE MIRROR ASSY | Cut | 1,013.16 FL | *1,013.16 FL |
| 2 | 1 | | *LH FRONT FENDER | Dented | 785.40 FL | *630.25 FL |
| 3 | 1 | | *LH FRONT FENDER ARCH MOULDING | Not Damaged | 189.70 FL | *- FL |
| 4 | 1 | | *LH FRONT DOOR | Not Damaged | 1,550.23 FL | *- FL |
| 5 | 1 | | *LH FRONT DOOR WEATHERSTRIP | Not Damaged | 155.60 FL | *- FL |
| 6 | 1 | | *LH FRONT DOOR PROTECTOR | Not Damaged | 281.34 FL | *- FL |
| 7 | 1 | | *LH REAR DOOR | Not Damaged | 1,487.60 FL | *- FL |
| 8 | 1 | | *LH REAR DOOR WEATHERSTRIP | Not Damaged | 134.75 FL | *- FL |
| 9 | 1 | | *LH REAR DOOR PROTECTOR | Not Damaged | 213.00 FL | *- FL |
| 10 | 1 | | *LH ROCKER PANEL SIDE SKIRTING | Not Damaged | 874.23 FL | *- FL |
| 11 | 1 | | *LH REAR FENDER | Not Damaged | 1,643.50 FL | *- FL |
| 12 | 1 | | *LH REAR FENDER GLASS WITH RUBBER MOULDING | Not Damaged | 715.80 FL | *- FL |
| 13 | 1 | | *LH REAR FENDER ARCH MOULDING | Not Damaged | 258.85 FL | *- FL |
| 14 | 1 | | *LH REAR SPORT RIM (ORIGINAL) | Cut | 1,151.37 FL | *1,151.37 FL |
| 15 | 1 | | *LH REAR WHEEL BEARING | Not Damaged | 155.80 FL | *- FL |
| 16 | 1 | | *LH REAR SHOCK ABSORBER | Not Damaged | 340.50 FL | *- FL |
| 17 | 1 | | *LH REAR LOWER ARM | Not Damaged | 347.55 FL | *- FL |
| 18 | 1 | | *LH REAR KNUCKLE ARM | Not Damaged | 1,106.95 FL | *- FL |
| 19 | 1 | | *LH REAR UPPER ARM | Not Damaged | 578.14 FL | *- FL |
| 20 | 1 | | *SET LH FRONT FENDER ARCH MOULDING CLIPS | Not Necessary | 80.00 FS | *-FS |
| 21 | 1 | | *SET LH REAR FENDER ARCH MOULDING CLIPS | Not Necessary | 80.00 FS | *-FS |
| 22 | 1 | | *SET LH FRONT DOOR INNER TRIM BOARD CLIPS | Not Necessary | 60.00 FS | *- FS |
| 23 | 1 | | *SET LH REAR DOOR INNER TRIM BOARD CLIPS | Not Necessary | 60.00 FS | *-FS |
| 24 | 1 | | *LH REAR FENDER GLASS SEALANT | Not Necessary | 70.00 FS | *-FS |
| 25 | 1 | | *LH REAR FENDER GLASS INNER SEAL | Not Necessary | 30.00 FS | *-FS |
| 26 | 1 | | *LH REAR TYRE | Not Necessary | 450.00 FS | *-FS |
| 27 | 1 | | *BRAKE FLUID | Not Necessary | 60.00 FS | *-FS |
| F=Fra | anchise | part. S=Spc | Nett. L=ListItemDisc. | - | | |
| | | | | Sub Total (S\$) | 13,873.47 | 2,794.78 |
| | - List Item Discount on L Items 5.00/5.00% (S\$) | | | | 649.17 | 139.74 |
| | | | | Total Parts (S\$) | 13,224.30 | 2,655.04 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|------------|------------|--------|
| <u>Lab</u> | our Items | | | |
| 1 | LABOUR CHARGE TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS | New | 1,500.00 | 300.00 |
| 2 | SPRAY PAINTING ON AFFECTED PANELS | New | 1,200.00 | 300.00 |
| 3 | CHECK WIRING AND LIGHTING SYSTEM | New | 80.00 | 0.00 |
| 4 | APPLY RUST COATING CHEMICAL ON AFFECTED PANELS | New | 100.00 | 0.00 |
| 5 | REMOVE AND REFIT LH FRONT DOOR INNER PARTS TO NEW DOOR | New | 120.00 | 0.00 |
| 6 | REMOVE, REFIT AND REPLACE LH REAR DOOR INNER PARTS TO NEW DOOR | New | 120.00 | 0.00 |
| 7 | REMOVE AND REFIT LH SIDE INNER GARNISH, TRIMS, SEATS AND ROOF LINING TO ASSIST REPAIRS | New | 480.00 | 0.00 |
| 8 | REMOVE AND REFIT LH REAR FENDER GLASS TO ASSIST REPAIR | New | 120.00 | 0.00 |
| 9 | CONDUCT AND ADJUST WHEEL ALIGNMENT SYSTEM | New | 120.00 | 0.00 |
| 10 | REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR | New | 350.00 | 0.00 |
| 11 | DIAGNOSE AND RESET ELECTRONIC CONTROL UNIT AND FAULT CODE AFTER REPAIR | New | 280.00 | 0.00 |
| | Gross Labour | 4,470.00 | 600.00 | |
| | | | | |
| 1 | Report was unsubmitted during this p | orint-out. | | |

< END OF ESTIMATES >