

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008099/JES3Q2
Date: 10/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBA6089B	Insured Vehicle No :	SLN4524M
Date of Loss:	29/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003245

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA6089B	Engine No:	199A20002001330
Make & Model:	FIAT DOBLO, 1.9 D (M)	Chassis No:	ZFA22300005527634
Reg. Date:	10/09/2007 (Man. Year: 2007)	Odometer:	311754 km
Colour:	White		
Engine Capacity:	1248 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Goodride 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,130.70	5,266.63	864.07	14.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,785.00	1,520.00	1,265.00	45.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,915.70	6,786.63	2,129.07	23.88
Approved Total (Overridden) (S\$)		4,500.00		

(S\$)	8,915.70	4,500.00	4,415.70	49.53
+ GST 7.00/7.00% (S\$)	624.10	315.00	309.10	49.53
Nett Amount (S\$)	9,539.80	4,815.00	4,724.80	49.53
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		5,115.00		

INSPECTION

Date of Assignment: 30/07/2021

Date Inspected: 02/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
Parts:	M1-MPV	FIAT DOBLO 1.9 D (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA6089B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Badly Dented	1,895.90 F	*1,895.90 FL
2	1		*REAR LH DOOR BADGE	Necessary	87.50 F	*87.50 FL
3	1		*REAR LH DOOR DOBLO EMBLEM	Necessary	95.00 F	*95.00 FL
4	1		*REAR RH DOOR	Badly Dented	2,056.30 F	*2,056.30 FL
5	1		*REAR RH DOOR MULTIJET EMBLEM	Necessary	90.00 F	*90.00 FL
6	1		*REAR BUMPER	Dented / Deformed	589.00 F	*589.00 FL
7	1		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
8	1		*REAR BUMPER REINFORCEMENT (NPA)	Repair	0.00 F	*- FL
9	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 F	*- FL
10	1		*RH BUMPER SIDE	Deformed / Torn	233.70 F	*233.70 FL
11	1		*RH SIDE WHITE GARNISH (NPA)	No such part	0.00 F	*- FL
12	1		*RH TAILLAMP	Cracked	310.70 F	*310.70 FL
13	1		*RH TAILLAMP BLACK GARNISH	Torn	154.40 F	*154.40 FL
14	1		*RH DOOR WEATHERSTRIP	Twisted	188.20 F	*188.20 FL
15	1		*REAR END PANEL (NPA)	Repair	0.00 F	*- FL
16	1		*REAR LH DOOR WEATHERSTRIP (NPA)	Not Necessary	0.00 F	*- FL
17	1		*REAR 70KM/H	Necessary	15.00 FS	*10.00 FS
18	1		*REAR DOOR 4 PAX	Necessary	15.00 FS	*10.00 FS
19	1		*REAR BUMPER REVERSE SENSOR	Serviceable	280.00 FS	*- FS
20	1		*SET SEALANT (REAR GLASS)	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,130.70	5,840.70
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	574.07
Total Parts (\$\$)	6,130.70	5,266.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSFER DOOR FITTING	New	60.00	60.00
2	REMOVE & REFIT REAR WINDSCREEN	New	240.00	200.00
3	SPRAY PAINTING	New	1,250.00	680.00
4	LABOUR CHARGE	New	1,100.00	500.00
5	TUFF COAT	New	100.00	60.00
6	WIRING CHECK	New	35.00	20.00
Gross Labour Cost (S\$)			2,785.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >