

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG21004716/EVF3E2-1

Date: 06/08/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001621713		
Claimant Vehicle No :	SJM5501B	Insured Vehicle No :	SLK3016K		
Date of Loss:	12/04/2021	Nature of Claim:	TP	Claim No:	255930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM5501B	Engine No:	L13A4161928
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61148159
Reg. Date:	08/01/2009 (Man. Year: 2008)	Odometer:	127348 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 4 mm	Rear Left Side:	Falken 4 mm
Front Right Side:	Falken 4 mm	Rear Right Side:	Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,068.40	5,469.12	12,599.28	69.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,720.00	3,430.00	2,290.00	40.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,788.40	8,899.12	14,889.28	62.59
Approved Total (Overridden) (S\$)		7,100.00		
Nett Amount (S\$)	23,788.40	7,100.00	16,688.40	70.15

INSPECTION

Date of Assignment:	14/04/2021	2020 Spray Painting Pte Ltd (HQ)
Date Inspected:	15/04/2021 Inspected At:	53 UBI AVE 1, #05-15 PAYA UBI INDUSTRIAL PARK
Estimated Period of Repair:	12.0 days	Singapore 408934

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2021)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM5501B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	416.90 FL	*416.90 FL
2	2		*FRONT BONNET HINGES L/R	Serviceable	59.60 FL	*- FL
3	1		*FRONT BONNET MECHANISM LOCK	Serviceable	115.30 FL	*- FL
4	1		*FRONT BONNET WEATHERSTRIP	Serviceable	30.00 FL	*- FL
5	1		*FRONT GRILLE	Cracked	137.50 FL	*137.50 FL
6	1		*FRONT GRILLE LOGO EMBLEM	Necessary	22.90 FL	*22.90 FL
7	4		*FRONT GRILLE CLIPS	Necessary	26.00 FL	*10.00 FL
8	2		*FRONT HEADLAMP L/R	Serviceable	1,170.00 FL	*- FL
9	2		*FRONT HEADLAMP CLIPS L/R	Serviceable	13.00 FL	*- FL
10	1		*FRONT BUMPER	Cracked	503.20 FL	*503.20 FL
11	1		*FRONT BUMPER LOWER AIR GRILLE	Cracked	150.80 FL	*150.80 FL
12	1		*FRONT BUMPER LOWER RUBBER SPOILER	Serviceable	105.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	222.20 FL	*222.20 FL
14	2		*FRONT BUMPER SIDE RETAINER L/R	Bent	27.00 FL	*27.00 FL
15	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	13.80 FL	*- FL
16	2		*FRONT FENDER L/R	Repair	733.20 FL	*- FL
17	2		*FRONT SUPPORT PANEL RUBBER GUIDE STOPPER L/R	Repair	36.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Repair	389.50 FL	*- FL
19	1		*AIRCON CONDENSER	Serviceable	733.20 FL	*- FL
20	1		*AIRCON COOLING PIPE	Repair	91.60 FL	*- FL
21	1		*AIRCON DISCHARGE PIPE	Repair	160.40 FL	*- FL
22	1		*HORN	Serviceable	46.70 FL	*- FL
23	1		*FRONT WASHER TANK	Repair	58.40 FL	*- FL
24	1		*FRONT DRIVER SEAT BELT	Serviceable	385.00 FL	*- FL
25	1		*FRONT CENTRE CONSOLE ASSY	Cracked	322.00 FL	*150.00 FL
26	1		*REAR TAILGATE	Bent	708.00 FL	*708.00 FL
27	1		*REAR TAILGATE FIT EMBLEM	Necessary	35.00 FL	*35.00 FL
28	1		*REAR TAILGATE LOGO EMBLEM	Necessary	60.10 FL	*60.10 FL
29	2		*REAR TAILGATE DAMPER L/R	Serviceable	218.60 FL	*- FL
30	2		*REAR TAILGATE HINGES L/R	Serviceable	59.60 FL	*- FL
31	1		*REAR TAILGATE NOZZLE	Serviceable	28.00 FL	*- FL
32	4		*REAR TAILGATE OUTER GARNISH CLIPS	Serviceable	26.00 FL	*- FL
33	1		*REAR TAILGATE OUTER HANDLE	Serviceable	56.70 FL	*- FL
34	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Serviceable	65.40 FL	*- FL
35	1		*REAR TAILGATE WINDSCREEN	Reuse	1,180.00 FL	*- FL
36	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	60.00 FL	*60.00 FL
37	1		*REAR TAILGATE WIPER ARM	Serviceable	58.00 FL	*- FL
38	1		*REAR TAILGATE WIPER ARM COVER	Serviceable	9.50 FL	*- FL
39	1		*REAR TAILGATE WIPER BLADE	Serviceable	48.00 FL	*- FL
40	1		*REAR TAILGATE WIPER MOTOR	Serviceable	238.00 FL	*- FL
41	1		*REAR TAILGATE INNER HANDLE	Serviceable	27.50 FL	*- FL
42	2		*REAR TAILGATE INNER TRIM BOARD	Cracked	220.00 FL	*220.00 FL
43	1		*REAR TAILGATE MECHANISM LOCK	Bent	186.20 FL	*186.20 FL
44	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Serviceable	21.00 FL	*- FL
45	1		*REAR TAILGATE WEATHER STRIP	Cut	92.30 FL	*92.30 FL
46	1		*REAR RH TAILLAMP	Repair	206.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	3		*REAR LH TAILLAMP CLIPS	Serviceable	19.50 FL	*- FL
48	1		*REAR LH TAILLAMP BRAKE BULB SOCKET	Serviceable	21.30 FL	*- FL
49	1		*REAR LH TAILLAMP REVERSE BULB SOCKET	Serviceable	18.10 FL	*- FL
50	1		*RAER LH TAILLAMP SIGNAL BULB SOCKET	Serviceable	13.50 FL	*- FL
51	1		*REAR LH TAILLAMP WIRE HARNESS	Serviceable	355.10 FL	*- FL
52	1		*REAR LH TAILLAMP INNER PANEL	Bent	206.60 FL	*206.60 FL
53	1		*REAR LH FENDER	Bent	626.70 FL	*626.70 FL
54	1		*REAR LH FENDER INNER TOP GARNISH	Repair	59.60 FL	*- FL
55	1		*REAR LH FENDER INNER TOP GARNISH CLIPS (6PCS)	Necessary	39.00 FL	*10.00 FL
56	1		*REAR LH FENDER INNER TRIM BOARD	Cracked	151.20 FL	*151.20 FL
57	1		*REAR LH FENDER INNER SHIELD	Serviceable	41.20 FL	*- FL
58	1		*REAR LH FENDER AIR VENT	Serviceable	26.00 FL	*- FL
59	1		*REAR LH DOOR	Repair	717.10 FL	*- FL
60	2		*REAR PASSENGER SEAT ASSY L/R	Repair	2,820.00 FL	*- FL
61	1		*REAR AXLE	Serviceable	982.00 FL	*- FL
62	1		*REAR LH WHEEL HOUSE ASSY	Serviceable	229.10 FL	*- FL
63	2		*REAR SHOCK ABSORBER L/R	Serviceable	500.00 FL	*- FL
64	2		*REAR SHOCK ABSORBER SPRING L/R	Serviceable	296.00 FL	*- FL
65	2		*REAR WHEEL BEARING L/R	Serviceable	500.00 FL	*- FL
66	1		*REAR BUMPER	Cracked	456.00 FL	*456.00 FL
67	2		*REAR BUMPER SIDE RETAINER L/R	Bent	33.00 FL	*33.00 FL
68	1		*REAR BUMPER TOW HOOK COVER	Necessary	12.60 FL	*12.60 FL
69	1		*REAR END PANEL INNER TOP GARNISH	Cracked	60.80 FL	*60.80 FL
70	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	26.00 FL	*10.00 FL
71	1		*REAR END PANEL	Bent	265.80 FL	*265.80 FL
72	1		*REAR END PANEL EXTENSION TOOL PANEL	Bent	135.00 FL	*135.00 FL
73	1		*REAR LH SUB CHASSIS FRAME	Serviceable	262.20 FL	*- FL
74	1		*SPARE TYRE PANEL INNER SPONGE TRAY	Serviceable	220.40 FL	*- FL
75	1		*SPARE TYRE PANEL TOP BOARD	Bent	183.90 FL	*183.90 FL
76	1		*SPARE TYRE LH SIDE PANEL	Bent	137.40 FL	*137.40 FL
77	1		*SPARE TYRE PANEL	Bent	737.00 FL	*737.00 FL
78	1		*REAR EXHAUST SILENCER BOX	Serviceable	446.80 FL	*- FL
79	1		*REAR TAILGATE OUTER GARNISH	Cracked	114.60 FL	*114.60 FL
80	1		*REAR LH TAILLAMP	Cracked	206.20 FL	*206.20 FL
81	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
82	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*20.00 FS
83	1		*FRONT NUMBER PLATE HOLDER	Cracked	50.00 FS	*30.00 FS
84	1		*REAR LH FENDER GLASS SEALANT	Necessary	80.00 FS	*30.00 FS
85	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Serviceable	30.00 FS	*- FS
86	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Repeated	60.00 FS	*- FS
87	1		*REAR LH TAILLAMP BRAKE BULB	Serviceable	12.00 FS	*- FS
88	1		*REAR LH TAILLAMP REVERSE BULB	Serviceable	10.00 FS	*- FS
89	1		*REAR LH TAILLAMP SIGNAL BULB	Serviceable	12.00 FS	*- FS
90	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*10.00 FS
91	1		*REAR TAILGATE NUMBER PLATE	Serviceable	25.00 FS	*- FS
92	1		*REAR TAILGATE NUMBER PLATE HOLDER	Serviceable	50.00 FS	*- FS
93	1		*REAR TAILGATE REVERSE CAMERA	Serviceable	800.00 FS	*- FS
94	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
95	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
96	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,167.00	6,738.90
- List Item Discount on L Items 20.00/20.00% (\$)	4,098.60	1,269.78
Total Parts (\$)	18,068.40	5,469.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGE	New	50.00	50.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	180.00	30.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET	New	150.00	80.00
4	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS	New	160.00	0.00
5	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
6	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	450.00	0.00
7	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	140.00	0.00
8	TO MOUNT VEHICLE ON TO CAR O LINER	New	400.00	0.00
9	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	0.00
10	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	1,500.00
11	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
12	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	1,600.00
Gross Labour Cost (S\$)			5,720.00	3,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >