

Date : 30 August 2019

To

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attn : Ms Juliana Lee

No.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155 info@ajaxinspection.com

Invoice No - AV20992 Company Reg No -201318067R

GST Reg No - 201318067R

RECEIVED

- 4 SEP 2019

MOTOR CLAIM

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1007785-002 108

OUR REF : AVS2018-16416/AT

TP VEHICLE NO : FBE1977A

CLAIM TYPE : PRE-REPAIR SURVEY

DATE OF SURVEY : 05 October 2018

Description Amount (S\$)

Professional fee 250.00

Subtotal 250.00 GST 7.00% 17.50 Total 267.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com





PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Susan Ting

Assign Date:

05/10/2018

Survey Date:

05/10/2018

Adjustment Date: 23/08/2019

Accident Date:

17/08/2018

TP Policy No:

NΔ

Our Ref:

AVS2018-16416/AT MT/1007785-002

Place of Survey: Equator Brotherhood

25 Kaki Bukit Road 4 #03-79 Synergy

Your Ref: Claim Type:

Third Party

Singapore

417800

Claimant:

Nicholas Lee Teck Shen

Description of Vehicle:

Veh. No:

FBE1977A

Make/Model:

Honda CB400

Colour:

White 399 cc **Engine No:**

NC23E2021008

Engine Capacity: Odometer:

NA

Chassis No: Reg. Date:

NC391021008 08/06/2001

Condition of Vehicle:

General:

Good

Modification:

No

Steering:

Affected

Handbrake:

Affected Footbrake: Affected

Paint work:

Good

Tyre Make:

Front Tyre Size:

Rear Tyre Size:

Metzeler

120/60R17 160/60R17 Front Side: Rear Side:

6mm 6mm

Description of Damage:

The vehicle sustained damage on the left portion.

The handlebar, handlebar grip, handlebar balancer, front fork assy, front signal lamp, rear signal lamp, fuel tank, front wheel rim, front mudguard, horn, brake lever, clutch lever, front number plate, IU unit, headlamp, crash bar, front footrest, rear footrest, tail fairing and seat were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is \$\$6,850.00 with approximately six (6) working days to complete. However, no finalisation was agreed with the repairer.

Adjuster:

Mohamad Affandi

Motor Appraiser

COMPLETED 28 AUG 2019

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



Adjus	stment	t of Repair Cost for Vehicle:	FBE1977A	Our Ref:	AVS2018-16416/A
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate \$\$	Our Recommendation S\$
ist It	tems				
1	1	Honda front suspension (left)	Repair	1,280.00	
2	1	Honda front suspension (right)	Bent	1,280.00	1,280.00
3	1	Honda front suspension cover (left)	Not Necessary	60.00	
4	1	Honda front suspension cover (right)	Broken	60.00	60.00
5	1	Honda steering cone bearing	Necessary	140.00	140.00
6	1	Honda tripe clamp (top)	Distorted	320.00	320.00
7	1	Honda triple clamp (bottom)	Distorted	395.00	395.00
8	1	Honda key ignition	Cracked	220.00	220.00
9	1	Honda meter	Cracked	980.00	980.00
10	1	Renthal handle bar (annodized)	Broken	220.00	220.00
11	1	Honda front rim	Repair	1,250.00	
12	1	Honda front wheel bearing	Necessary	80.00	80.00
13	1	Honda front wheel seal	Necessary	30.00	30.00
14	1	Honda front wheel shaft	Distorted	120.00	120.00
15	1	Honda front headlight	Missing	680.00	680.00
16	1	Honda crash bar	Grazed	180.00	180.00
17	1	Honda headlight bracket (left)	Broken	115.00	115.00
18	1	Honda headlight bracket (right)	Broken	115.00	115.00
19	1	Honda headlight bracket (center)	Bent	85.00	85.00
20	1	Honda front brake disc (left)	Not Necessary	680.00	
21	1	Honda front brake disc (right)	Not Necessary	680.00	
22	1	Honda front brake pad	Not Necessary		
23	1	Honda front brake master cylinder	Not Necessary	320.00	
24	1	Honda front brake hoses	Not Necessary	195.00	
25	1	Honda throttle cable	Not Necessary	160.00	
26	1	Honda starter switch	Grazed	220.00	220.00
27	1	Honda throttle tube	Not Necessary	45.00	
28	1	Honda front mudguard	Cracked	280.00	280.00
29	1	Honda handle bar clamp	Bent	120.00	120.00
30	1	Honda rider footrtest (left)	Grazed	75.00	75.00
31	1	Honda rider footrest rubber (left)	Cut	15.00	15.00
32	1	Honda rider footrest spring (left)	Not Necessary	15.00	13.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation \$\$
33	1	Honda rider footrest pin (left)	Broken	15.00	15.00
34	1	Honda pillion footrest bracket (left)	Not Necessary		
35	1	Honda pillion footrest (left)	Broken	55.00	55.00
36	1	Honda clutch lever holder	Broken	80.00	80.00
37	1	Honda clutch lever holder screw	Necessary	15.00	15.00
38	1	Honda clutch cable	Not Necessary	55.00	
39	1	Honda clutch adjuster screw	Not Necessary	25.00	
40	1	Honda radiator	Not Necessary	650.00	
41	1	Honda radiator protector	Not Necessary		
42	1	Honda rear number plate holder	Not Necessary	220.00	
43	1	Honda rear tail light	Not Necessary	380.00	
44	1	Honda tail fairing	Cracked	280.00	280.00
45	1	Honda beliy pan	Repair	150.00	
46	1	Honda side cover (left)	Not Necessary	135.00	
47	1	Honda side cover (right)	Not Necessary		
48	1	Honda fuel tank	Dented	980.00	980.00
49	1	Koso voltmeter	Not Necessary	55.00	55.00
50	1	Hella twin tone horn	Cracked	65.00	65.00
51	1	Honda HISS key receiver (top of key ignition)	Not Necessary	180.00	
52	1	CNC pillion holder cover	Not Necessary	55.00	
53	1	GPR front signal light set	Broken	70.00	70.00
54	1	GPR rear signal light set	Broken	70.00	70.00
55	1	Motovation heavy bar end	Broken	120.00	120.00
56	1	Honda HISS key	Not Necessary	160.00	221
57	1	Gear shift pedal	Not Necessary	75.00	
58	1	Honda brake lever	Cracked	80.00	80.00
59	1	Side mirror	Missing	190.00	190.00
50	1	Honda brake cable	Not Necessary	220.00	
61	1	Honda headlamp swtich	Cracked	212.00	212.00
62	1	Honda clutch lever	Cracked	55.00	55.00
		A	Sub Total:	15,062.00	8,072.00
		Dis	count (less 10%):	1,506.20	807.20

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
Speci	al Net	t Items			
1	1	IU unit	Cracked	156.00	156.00
2	1	IU bracket	Bent	35.00	35.00
3	1	LiquiMoly RAF 12+ coolant	Not Necessary	65.00	-
4	1	Front number plate	Bent	15.00	15.00
5	1	Rear number plate	Not Necessary	20.00	-
6	1	Honda seat wrap	Not Necessary	60.00	
			Sub Total:	351.00	206.00
			Total Parts Price:	13,906.80	7,470.80

1	To remove & replace front rim, front wheel bearing, axle shaft, front fork, tripple clamps, front fork, steering cone, front brake disc.	280.00	250.00
2	To remove & replace above body damaged parts and check lighting system.	500.00	250.00
3	To respray paint on the affected area.	400.00	300.00
4	Chassis alignment (front).	350.00	200.00
5	To remove and replace radiator, radiator fan, coolant and conduct pressure test.	80.00	55.1
6	Towing front traffic police compound to workshop.	60.00	40.00
7	Towing workshop to accident reporting center.	60.00	40.00
8	Towing accident reporting center to workshop.	60.00	40.00
	Sub Total:	1,790.00	1,120.00
	Grand Total:	15,696.80	8,590.80



Our Ref:

AVS2018-16416/AT

Your Ref:

MT/1007785-002

Post repair survey - 21/11/2018









AJAX