



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206990

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/11/2022
Reference CC6/CTI21008105/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLU 3970C
Insured Veh. SGR 158B
Claim No. SNM21D204293/C02
Policy No. DMHCSNW00001142100
Accident Date 24/07/2021
Inspection Date 28/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21008105/Apa3q2	
			Date: 10/11/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGR 158B	Veh. Inspected	SLU 3970C	
Policy No.	DMHCSNW00001142100	Coverage (\$)	0.00	
Claim No.	SNM21D204293/C02	Excess (\$)	0.00	
Assign From		Assign Date	28/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	OPEL MOKKA	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	W0LJD7EC0HB148796	Colour	SILVER	
Odometer	285507 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/65 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/65 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/65 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2021	Inspection Date	28/07/2021	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 3970C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RR BUMPER UPP	DEFORMED	1,485.00	1,485.00
1	RR BUMPER LOW	DEFORMED	750.00	750.00
1	RR BUMPER SIDE RETAINER RH	NECESSARY	145.00	145.00
1	RR BUMPER SIDE RETAINER LH	NECESSARY	145.00	145.00
1	RR BUMPER BRACKET LOW RH	NOT NECESSARY	115.00	-
1	RR BUMPER BRACKET LOW LH	NOT NECESSARY	115.00	-
1	RR BUMPER COVER LOW (SILVER)	DEFORMED	273.00	273.00
1	RR BUMPER TOW COVER	DEFORMED	112.00	112.00
1	RR BUMPER REFLECTOR RH	CRACKED	122.00	122.00
1	RR BUMPER REFLECTOR LH	NOT NECESSARY	122.00	-
1	RR BUMPER REINFORCEMENT	BENT	842.00	842.00
1	REAR BUMPER ABSORBER -RH	DEFORMED	52.00	52.00
1	REAR BUMPER ABSORBER -LH	NOT NECESSARY	52.00	-
2	RR BUMPER REVERSE SENSOR	DAMAGED (1 PCS ONLY)	532.00	266.00
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	277.00	-
1	RR TAILGATE	NOT NECESSARY	1,942.00	-
1	RR TAILGATE INNER TRIM BOARD LOWER	NOT NECESSARY	314.00	-
1	RR TAILGATE OUTER HANDLE ASSY	NOT NECESSARY	270.00	-
1	RR TAILGATE NUMBER PLATE LAMP	NOT NECESSARY	130.00	-
1	RR TAILGATE MOKA X EMBLEM	NECESSARY	109.00	109.00
1	RR TAILGATE OPEL LOGO	NECESSARY	162.00	162.00
1	RR TAILGATE CDTI EMBLEM	NECESSARY	109.00	109.00
1	RR WINDSCREEN MLDG	NOT NECESSARY	818.00	-
1	RR TAILGATE WEATHERSTRIP	NOT NECESSARY	190.00	-
1	REAR TAIL LID LATCH	NOT NECESSARY	140.00	-
1	REAR TAIL LID STRIKER	NOT NECESSARY	18.00	-
1	RR END PANEL	TO REPAIR SEE LABOUR	1,390.00	-
1	REAR END PANEL TRIM	NOT NECESSARY	164.00	-
1	RR FENDER RH	NOT NECESSARY	3,110.00	-

Report Ref No. CC6/CTI21008105/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR FENDER AIR DUCT RH	NOT NECESSARY	115.00	-
1	RR FENDER INNERSHIELD RH	NOT NECESSARY	237.00	-
1	RR FENDER INNER TRIM BOARD RH	NOT NECESSARY	600.00	-
1	RR FENDER WHEELARCH GARNISH RH	NOT NECESSARY	162.00	-
1	RR TAILLAMP RH	NOT NECESSARY	564.00	-
1	RR TAILLAMP CLIP	NOT NECESSARY	46.00	-
1	RR TAILLAMP PANEL RH	NOT NECESSARY	110.00	-
1	RR TAILLAMP LH	NOT NECESSARY	564.00	-
1	RR EXHAUST SILENCER BOX	NOT NECESSARY	2,164.00	-
1	RR EXHAUST SILENCER BOX MOUNTING	NOT NECESSARY	148.00	-
1	RR EXHAUST PIPE CLAMP	NOT NECESSARY	168.00	-
	LESS 10% DISCOUNT		-1,888.30	-457.20
			16,994.70	4,114.80
	<u>SPECIAL NETT ITEMS</u>			
10	RR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
5	RR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	40.00	-
1	RR WINDSCREEN SEALANT (SN)	NOT NECESSARY	65.00	-
1	RR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	45.00	-
1	RR WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	250.00	-
			460.00	30.00
	<u>LABOUR</u>			
	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF RR END PANEL .		1,200.00	400.00
	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR TAILGATE ,RR END PANEL,RR FENDER RH .		1,200.00	600.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		120.00	30.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		100.00	40.00
	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY &ROOF LINING TO FACILITATE REPAIRS.		160.00	50.00

Report Ref No. CC6/CTI21008105/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		100.00	50.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.	NOT NECESSARY	100.00	-
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.	NOT NECESSARY	160.00	-
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.	NOT NECESSARY	180.00	-
			3,600.00	1,170.00
GRAND TOTAL			21,054.70	5,314.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CC6/CTI21008105/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 3970C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 3970C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

