

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21008106/AUCN2**Date:** 13/10/2021**REFERENCE**

Insured/Claimant: ANG YUAN PIN(HONG YUANBIN) Policy No: 2100479292  
Date of Loss: 22/07/2021 Nature of Claim: OD Claim No: 8773114089SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLE6941B**  
Make & Model: AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A) Engine No: CZC556146  
Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: WAUZZZ8V7G1099550  
Colour: White Odometer: 99601 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$65,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,480.00	1,708.96	1,771.04	50.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	2,222.00	1,650.00	42.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,352.00</b>	<b>3,930.96</b>	<b>3,421.04</b>	<b>46.53</b>
<b>- Excess (S\$)</b>	200.00	200.00	0.00	0.00
<b>(S\$)</b>	7,152.00	3,730.96	3,421.04	47.83
<b>+ GST 7.00/7.00% (S\$)</b>	500.64	261.17	239.47	47.83
<b>Nett Amount (S\$)</b>	<b>7,652.64</b>	<b>3,992.13</b>	<b>3,660.51</b>	<b>47.83</b>

**INSPECTION**

Date of Assignment: 02/08/2021  
Date Inspected: 28/07/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,070.00 FS	*1,656.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION LH/RH	Not Necessary	32.00 FS	*- FS
4	1		*REAR LIGHT REFLECTOR LH	Not Necessary	41.00 FS	*- FS
5	1		*LED TAIL LIGHT LH	Not Necessary	877.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION LH UPPER	Cracked	67.00 FS	*52.96 FS
7	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					3,480.00	1,708.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	650.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,872.00</b>	<b>2,222.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >