

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Re	f: CC4/ASM21008107/Dga3q2	
	8 SHENTON WAY AXA TOWERSING		Da	te: 18/01/2022	
	ATTN:CHAN KIAN	CHUAN	Co	de: ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1963D	Veh. Inspected	VCT 3242	
	Policy No.	P2419138	Coverage (\$)	0.00	
	Claim No.	S1M0383O	Excess (\$)	0.00	
	Assign From		Assign Date	22/04/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA 135LC	c.c	134	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	PMYUG0810K0084748	Colour	GREEN	
	Odometer	22463 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	70/90 R17	PIRELLI	2 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	70/90 R17	PIRELLI	2 mm	
	L/H Rear Tyre			mm	
4.	. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT & O/S FRONT AND N/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	27/03/2021	Inspection Date	22/04/2021	
	Survey held at	SG 98 MOTOR PTE LTD	•		
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				