

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21008108/GQCEN2**Date:** 18/11/2021**REFERENCE**

Insured/Claimant:	CHEN CHIH MIN	Policy No:	2070017408	
Date of Loss:	26/07/2021	Nature of Claim:	OD	Claim No: 1445153367SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3016G		
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Engine No:	CVK087199
Reg. Date:	20/02/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF4XKA113735
Colour:	White	Odometer:	26730 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$136,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,926.00	2,711.60	24,214.40	89.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,472.00	2,272.00	3,200.00	58.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,398.00	4,983.60	27,414.40	84.62
- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
(S\$)	31,298.00	3,883.60	27,414.40	87.59
+ GST 7.00/7.00% (S\$)	2,190.86	271.85	1,919.01	87.59
Nett Amount (S\$)	33,488.86	4,155.45	29,333.41	87.59

INSPECTION

Date of Assignment:	02/08/2021		
Date Inspected:	30/07/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,787.00 FS	*1,429.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	587.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Broken	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	210.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cut	1,332.00 FS	*1,065.60 FS
7	2		*FRONT AIR GUIDE GRILLE LH/RH	Not Necessary	270.00 FS	*- FS
8	1		*FRONT FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
9	1		*FRONT REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
10	1		*FRONT BUMPER COVER	Not Necessary	127.00 FS	*- FS
11	1		*SIGN CAUTION STICKER	Not Necessary	14.00 FS	*- FS
12	1		*AIR CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
13	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
14	2		*FRONT LOCK CARRIER SUPPORT LH/RH	Not Necessary	58.00 FS	*- FS
15	2		*FRONT SENSOR INNER/OUTER (NPA)	Not Necessary	0.00 FS	*- FS
16	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
17	2		*FRONT HORN LH/RH	Not Necessary	252.00 FS	*- FS
18	2		*FRONT HORN BRACKET LH/RH	Not Necessary	58.00 FS	*- FS
19	1		*BONNET	Repair	3,246.00 FS	*- FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
21	1		*BONNET IMPACT PROTECTION CENTER	Not Necessary	28.00 FS	*- FS
22	2		*BONNET IMPACT PROTECTION LH/RH	Not Necessary	56.00 FS	*- FS
23	1		*BONNET BOWDEN RELEASE CABLE	Not Necessary	58.00 FS	*- FS
24	1		*BONNET BOWDEN CABLE CENTER	Not Necessary	58.00 FS	*- FS
25	1		*BONNET RELEASE CABLE COVER	Not Necessary	10.00 FS	*- FS
26	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
27	2		*BONNET STRIKER LH/RH	Not Necessary	100.00 FS	*- FS
28	2		*BONNET LID LOCK	Not Necessary	427.00 FS	*- FS
29	2		*LED HEADLIGHT LH/RH	Not Necessary	15,386.00 FS	*- FS
30	2		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM LH/RH	Not Necessary	420.00 FS	*- FS
31	1		*CORRUGATED PIPE FOR WASHER SYSTEM	Not Necessary	93.00 FS	*- FS
32	2		*RADIATOR AIR GUIDE LH/RH	Not Necessary	56.00 FS	*- FS
33	2		*RADIATOR AIR GUIDE LH/RH INNER	Not Necessary	24.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE UPPER	Not Necessary	16.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE LOWER	Not Necessary	22.00 FS	*- FS
36	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 26,926.00 2,711.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFR BOTH HEADLIGHTSS CONTROL UNIT AND POWER MODULE	New	700.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND BOTH HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,472.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >