

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21008109/VVF3E2**Date:** 12/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800128630
<b>Claimant Vehicle No :</b>	GBH5328G	<b>Insured Vehicle No :</b>	GBH9401B
Date of Loss:	27/07/2021	Nature of Claim:	TP
		Claim No:	1181583960SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBH5328G</b>		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2802143
Reg. Date:	02/07/2018 (Man. Year: 2018)	Chassis No:	JTFAT35Y90K210622
Colour:	Blue	Odometer:	58869 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

Date of Assignment:	02/08/2021	
Date Inspected:	04/08/2021 Inspected At:	TRISTAR ENGINEERING PTE LTD (HQ) 1 Kaki Bukit Avenue 6 #01-106 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$60,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER STEP PANEL	Bent	0.00 F	*- F
2	1		*TAILGATE	Bent	0.00 F	*- F
3	1		*REAR SIDEGATE LH	Bent	0.00 F	*- F
4	1		*REAR SIDEGATE LOCK LH	Distorted	0.00 F	*- F
5	1		*SIDEGATE RAILING LH	Repair	0.00 F	*- F
6	1		*STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >