

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008117/AVCN2**Date:** 20/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00095282004

Claimant Vehicle No : SMC8458R **Insured Vehicle No :** GBC5035C

Date of Loss: 30/07/2021 Nature of Claim: TP Claim No: SNM21D204222/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC8458R**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHC0703

Reg. Date: 25/07/2018 (Man. Year: 2018) Chassis No: MMBSTA13AJH002500

Colour: Black Odometer: 210849 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,576.00	4,032.55	2,543.45	38.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,140.00	1,590.00	42.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,306.00	6,172.55	4,133.45	40.11
Approved Total (Overridden) (\$\$)		4,900.00		
Nett Amount (\$\$)	10,306.00	4,900.00	5,406.00	52.45

INSPECTION

Date of Assignment: 09/08/2021

Date Inspected: 02/08/2021 Inspected At: Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Aug 2021)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC8458R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	708.00 F	*708.00 FL
2	1		*REAR BUMPER SIDE HOLDER RH	Damaged	26.00 F	*26.00 FL
3	1		*TAILLAMP RH	Cut	276.40 F	*276.40 FL
4	1		*TAILLAMP PANEL RH	Not Necessary	245.40 F	*- FL
5	1		*REAR RH FENDER	Distorted	798.00 F	*798.00 FL
6	1		*REAR RH FENDER INNER SHIELD	Torn	58.10 F	*58.10 FL
7	1		*REAR RH FENDER INNER TRIM	Not Necessary	181.70 F	*- FL
8	1		*REAR RH DOOR	Distorted	831.00 F	*831.00 FL
9	1		*REAR RH DOOR LOCK	Damaged	186.40 F	*186.40 FL
10	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	168.80 F	*- FL
11	1		*REAR RH DOOR INNER TRIM BOARD	Cracked	495.00 F	*495.00 FL
12	1		*REAR RH DOOR HANDLE	Repair	148.60 F	*- FL
13	1		*REAR RH DOOR GLASS REGULATOR GEAR	Damaged	185.60 F	*185.60 FL
14	1		*REAR RH DOOR GLASS REGULATOR MOTOR	Not Necessary	352.00 F	*- FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	105.00 F	*105.00 FL
16	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
17	1		*REAR BUMPER LOWER SPOILER	Torn	850.00 FS	*600.00 FS
18	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	10.00 FS	*10.00 FS
19	1		*REAR RH FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
20	1		*REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
21	1		*REAR RH WHEEL RIM	Not Necessary	800.00 FS	*- FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,576.00	4,399.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	366.95
Total Parts (\$\$)	6,576.00	4,032.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,400.00	900.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO SPRAY TUFF COAT	New	150.00	100.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
8	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			3,730.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >