# LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 Ubi Avenue 1 408933

Insurer Reference: SJJ6766M Repairer Reference: 042614

Repairer Reference: 042614 Registration: SJJ6766M Date calculated: 24/09/2021 8:46 AM Printed: 24/09/2021 8:46 AM

## **Summary Information**

Claim

Location: Singapore (SG) Work Provider: China Taiping Insurance

(Singapore) Pte Ltd SGD

30/07/21

**Full Report** 

Printed by: KK LAU Claim Reference: SJJ6766M

Date of Incident: Hire Car Start:

Hire Car Start: Hire Car End:

Currency:

**Vehicle Details** 

Actual Repair Days:

Estimated Repair Time:

Vehicle

Manufacturer: HYUNDAI Model: AVANTE (HD)

Sub Model: BASIS
Model Sheet Number: 30 22 50
Registration: SJJ6766M

VIN number: KMHDU41BMAU963523

Odometer:

**Model Specs** 

AIR CONDITIONING 1.6 LTR 90 KW 4-SPEED AUTOMATIC


### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

### **Damage Areas**

All	
Underbody	



## **Tyres Condition**

Tyre Brand Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Outer),

mm mm mm mm Middle), mm

Spare Tyre Brand

Tread (Spare), mm

#### Labour

Time Base 10 WU/h		Price = 42.	•
Code	Description	WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: BUMPER AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: REINFORCEMENT BUMPER REMOVE AND REFIT	8.0	33.60
92000R0B	REMOVE/REFIT BOTH HEADLIGHT UNITS INCLUDES: SET HEADLIGHT BEAMS	3.0	12.60
66300R5A	R + R RIGHT FRONT WING	7.0	29.40
NO NUMBER	R + R RIGHT FRONT WING BADGE	2.0	8.40
NO NUMBER	R + R FRONT PANEL	20.0	84.00
97606R00	R + R AIR CONDITIONING CONDENSER	10.0	42.00
25300R00)	R + R RADIATOR INCLUDES: $R + R$ COMPLETE RADIATOR SHROUD	7.0	29.40
25300RA4	ADD/WORK FOR AUTOMATIC GEARBOX	1.0	4.20
NO NUMBER	DRAIN/REFILL COOLING SYSTEM	3.0	12.60
09760A00	DRAIN + REFILL AIR CONDITIONING	5.0	21.00

	Total of Labour				277.20
Paint					
Paint Work	SYSTEM AZT		Tin	ne Basis	s 10 WU/h
Code	Description			WU	Price SGD
	R/F WING NEW PART PAINTING FRONT BUMPER NEW PART PAINT K1G/P			9.0 22.0	
Paint Mater	ial Per Part				
Code	Description				Price SGD
0742	R/F WING NEW PART PAINTING				14.11
0283	FRONT BUMPER NEW PART PAINT K1G/P				72.77
	<b>Labour Cost - Paint</b> Factor	42.00 SGD/h	Hrs	wu	Price SGD
	Time Paint	42.00 3GD/11		31.0	
	Preparation Main Work Metal		0.60	6.0	25.20
	Preparation Comp. Work Plastic <b>Total</b>	10 WU/h	1.00 4.70	10.0 47.0	42.00 197.40
	Material Cost - Paint				Price SGD
	New Part Painting				14.11
	New Part Painting - Plastic K1G/PUR				72.77
	Material constant Metal				12.70 16.20
	Material-constant Plastic <b>Total</b>				115.78
Spare Par	ts				
			prices	s as at 2	2015-06-01

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
0283 1009 0742 0812 0562	FRONT BUMPER INNER FRT PANEL CPL R/F WING R/F WING BADGE RIGHT HEADLAMP ASSY	865112H000 641012H000 663212H022 863162H000 921022H090	Original Original Original Original Original	280.00 480.00 250.00 30.00 300.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Subtotal Discount(+ Fixed Sundry Parts			0.00 1,340.00 -268.00 100.00
	Total			1,172.00

**Labour Cost** 

**Panel / Mechanical Labour** 

WU

66.0

277.20

Hrs

6.60

## **Final Calculation**

	SGD	SGD
Parts	1,340.00	
Total Discount(+20.00%)	-268.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,172.00
Labour Time Base 10 WU/h		
Total 66.0 WU X 42.00 SGD/h	277.20	
Total of Labour		277.20
Paint Work Time Base 10 WU/h		
Labour Cost 47.0 WU X 42.00 SGD/h	197.40	
Material Cost	115.78	
Total Paint Including Material		313.18
Repair Cost Excludes GST		1,762.38
GST (+7.00%)		123.37
Repair Cost Included GST		1,885.75

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

No assessment notes entered.