

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21008119/UES3Q2
Date: 10/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100288498
Claimant Vehicle No :	SCX7343C	Insured Vehicle No :	GBB6124C
Date of Loss:	31/07/2021	Nature of Claim:	TP
		Claim No:	3090190500SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCX7343C		
Make & Model:	HONDA CR-V, 2.4 (A)	Engine No:	R20A13700208
Reg. Date:	28/05/2009 (Man. Year: 2008)	Chassis No:	JHLRE28309C200238
Colour:	Silver	Odometer:	472442 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,007.68	1,225.76	781.92	38.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	800.00	610.00	43.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,417.68	2,025.76	1,391.92	40.73
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	3,417.68	1,600.00	1,817.68	53.18
+ GST 7.00/7.00% (S\$)	239.24	112.00	127.24	53.19
Nett Amount (S\$)	3,656.92	1,712.00	1,944.92	53.18
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,012.00		

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 03/08/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	570.20 FL	*570.20 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Bent	16.90 FL	*16.90 FL
4	1		*FRONT BUMPER RH SIDE BLACK TRIM	Deformed	32.10 FL	*32.10 FL
5	1		*FRONT RH BEAM (BELOW HEADLAMP)	Not Necessary	38.20 FL	*- FL
6	1		*FRONT RH FENDER	Buckled	636.80 FL	*636.80 FL
7	1		*FRONT RH FENDER BLACK TRIM MOULDING	Distorted	97.50 FL	*97.50 FL
8	1		*FRONT RH FENDER SHIELD	Deformed	139.70 FL	*139.70 FL
9	1		*FRONT RH HEADLAMP	Not Necessary	939.20 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	2,509.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	501.92
					Total Parts (S\$)	2,007.68
						1,532.20
						306.44
						1,225.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	580.00	400.00
2	LABOUR CHARGE	New	680.00	350.00
3	WIRING CHECKING	New	30.00	20.00
4	TUFF COAT	New	120.00	30.00
Gross Labour Cost (\$\$)			1,410.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >