

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21008122/R1ES3Q2
Date: 18/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900004396
Claimant Vehicle No :	SMR8263G	Insured Vehicle No :	FK311Z
Date of Loss:	01/08/2021	Nature of Claim:	TP
		Claim No:	6589432272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8263G		
Make & Model:	VOLKSWAGEN GOLF, 1.2 TSI (A)	Engine No:	CZCC08126
Reg. Date:	23/01/2020 (Man. Year: 2019)	Chassis No:	WVWZZZAUZLW008049
Colour:	Blue	Odometer:	15576 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,228.84	2,466.28	762.56	23.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,840.00	2,480.00	33.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,548.84	7,306.28	3,242.56	30.74
+ GST 7.00/7.00% (S\$)	738.42	511.44	226.98	30.74

Nett Amount (S\$)	11,287.26	7,817.72	3,469.54	30.74
		+ Loss of Use (7.0 x S\$60.00/day) (S\$)	420.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	8,239.72	

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 03/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,303.20 FS	*1,303.20 FS
2	1		*GUIDE PIECE (LHR BUMPER BRACKET)	Necessary	40.52 FS	*40.52 FS
3	1		*GUIDE PIECE (LHR BUMPER RETAINER)	Not Necessary	40.52 FS	*- FS
4	1		*ATTACHMENT STRIP	Not Necessary	69.96 FS	*- FS
5	1		*BUMPER (REINFORCEMENT)	Not Necessary	650.77 FS	*- FS
6	1		*REFLECTOR	Cracked	75.05 FS	*75.05 FS
7	1		*SENSOR BRACKET	Necessary	12.71 FS	*12.71 FS
8	1		*SENSOR BRACKET	Necessary	13.20 FS	*13.20 FS
9	1		*SENSOR BRACKET	Necessary	12.71 FS	*12.71 FS
10	1		*SENSOR BRACKET	Necessary	12.71 FS	*12.71 FS
11	1		*SENSOR PRIMED	Missing	178.20 FS	*178.20 FS
12	1		*SEAL RING SATIN BLACK	Not Necessary	1.31 FS	*- FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	65.18 FS	*65.18 FS
14	1		*2K-PLASTIC ADHESIVE	Necessary	81.16 FS	*81.16 FS
15	1		*LED TAIL LIGHT	Cracked	591.48 FS	*591.48 FS
16	1		*INSCRIPTION BRIGHT CHROME (GOLF)	Necessary	80.16 FS	*80.16 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	3,228.84	2,466.28
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR R	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	3,200.00	2,400.00
Gross Labour Cost (S\$)			7,320.00	4,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >