

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21008127/URA3Q2

Date:

19/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MCV0001739_01

Claimant Vehicle No : JNB5121**Insured Vehicle No :**

PC5900P

Date of Loss: 23/06/2021

Nature of Claim:

TP

Claim No:

MCV2021D0002692

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **JNB5121**

Make & Model: HONDA ACCORD, 2.4 (A)

Engine No:

K24Z249770092

Reg. Date: 15/08/2011 (Man. Year: 2011)

Chassis No:

PMHCP2640BD600109

Colour: Silver

Odometer:

304793 km

Engine Capacity: 2354 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50Z R17

Rear Tyre Size:

225/50Z R17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,029.00	5,315.20	8,713.80	62.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,230.00	1,090.00	32.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,349.00	7,545.20	9,803.80	56.51
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	17,349.00	6,000.00	11,349.00	65.42
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 02/08/2021

Date Inspected: 02/08/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2021)
Parts:	143	HONDA ACCORD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JNB5121)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	825.20 F	*667.80 FL
2	1		*FRONT BUMPER BEAM	Dented	322.50 F	*305.00 FL
3	1		*FRONT BUMPER TOP RETAINER	Bent	122.30 F	*121.00 FL
4	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	65.00 F	*65.00 FL
5	1		*FRONT BUMPER FOG LAMP O/S	Broken	285.50 F	*285.50 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*FRONT BUMPER PDC SENSOR O/S	Missing	220.00 F	*180.00 FL
8	1		*FRONT GRILLE	Cracked	485.00 F	*292.30 FL
9	1		*FRONT GRILLE LOGO	Necessary	54.00 F	*38.00 FL
10	1		*HEADLAMP O/S	Broken	1,600.20 F	*880.20 FL
11	1		*HEADLAMP LOWER BRACKET O/S	Cracked	98.20 F	*48.50 FL
12	1		*FRONT SUPPORT PANEL	Bent	745.20 F	*615.20 FL
13	1		*AIR CON CONDENSER	Not Necessary	911.20 F	*- FL
14	1		*RADIATOR	Not Necessary	1,625.20 F	*- FL
15	1		*FRONT FENDER O/S	Buckled	615.20 F	*488.30 FL
16	1		*FRONT FENDER INNER SHIELD O/S	Torn	218.80 F	*162.20 FL
17	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	39.00 F	*39.00 FL
18	1		*FRONT SHOCK ABSORBER O/S	Serviceable	425.50 F	*- FL
19	1		*FRONT LOWER ARM O/S	Serviceable	345.50 F	*- FL
20	1		*FRONT KNUCKLE ARM O/S	Damaged	455.20 F	*392.50 FL
21	1		*FRONT KNUCKLE ARM BEARING O/S	Damaged	195.00 F	*195.00 FL
22	1		*WIPER WASHER TANK	Distorted	184.20 F	*184.20 FL
23	1		*WIPER WASHER TANK MOTOR	Distorted	160.50 F	*160.50 FL
24	1		*FRONT WHEEL HOUSING PANEL	Distorted / Cracked	945.20 F	*911.30 FL
25	1		*FRONT WIRE HARNESS ASSY	Repair	1,200.00 F	*- FL
26	1		*BONNET	Repair	785.40 F	*- FL
27	1		*FRONT SPORT RIM O/S	Cut / Bent	850.00 FS	*450.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT TYRE O/S	Serviceable	200.00 F	*- FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					14,029.00	6,531.50
- List Item Discount on L Items 0.00/20.00% (\$)					0.00	1,216.30
Total Parts (\$)					14,029.00	5,315.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED FRONT PDC SENSOR	New	80.00	50.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	150.00	120.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	900.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,320.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >