

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21008130/BGA3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0004773
Claimant Vehicle No :	YP6414U	Insured Vehicle No :	CB8025E
Date of Loss:	29/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003254

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP6414U	Engine No:	4JJ12Z2779
Make & Model:	ISUZU NPR85UH5A, 3.0 D (M)	Chassis No:	JAANPR85HH7100435
Reg. Date:	26/04/2017 (Man. Year: 2017)	Odometer:	335441 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,159.11	2,584.74	10,574.37	80.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,300.00	1,650.00	55.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,109.11	3,884.74	12,224.37	75.88
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	16,109.11	3,100.00	13,009.11	80.76
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 02/08/2021

Date Inspected: 02/08/2021

Inspected At:

1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)
 8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Sep 2021)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6414U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,976.00 FL	*1,200.00 FL
2	1		*FRONT DOOR INNER PANEL RH	Broken	456.00 FL	*316.00 FL
3	1		*FRONT DOOR POWER WINDOW MOTOR RH	Jammed	556.00 FL	*165.00 FL
4	1		*FRONT DOOR GLASS RH	Not Damaged	844.40 FL	*- FL
5	1		*FRONT DOOR HANDLE RH (INNER)	Dislodged	274.10 FL	*215.00 FL
6	1		*FRONT DOOR UPPER LOCK	Jammed	257.00 FL	*185.00 FL
7	1		*FRONT DOOR LOCK STRIKER RH	Not Damaged	189.00 FL	*- FL
8	1		*FRONT DOOR GLASS REGULATOR RH	Bent	347.10 FL	*238.00 FL
9	1		*FRONT DOOR RUBBER STOPPER RH	Not Damaged	122.00 FL	*- FL
10	1		*FRONT DOOR CABIN PILLAR RH	Not Damaged	1,845.50 FL	*- FL
11	1		*FRONT DOOR STEP GARNISH RH	Broken	149.70 FL	*145.70 FL
12	1		*FRONT DOOR STEP GARNISH PROTECTOR RH	Broken	165.90 FL	*165.90 FL
13	1		*FRONT DOOR SIDE SIGNAL LAMP RH	Not Damaged	117.00 FL	*- FL
14	1		*FRONT DOOR WHEEL ARCH PANEL RH	Dented	208.00 FL	*208.00 FL
15	1		*SIDE GATE PANEL RH	Not Damaged	2,915.20 FL	*- FL
16	1		*FRONT BUMPER	Repair	917.00 FL	*- FL
17	1		*FRONT SHOCK ABSORBER RH	Not Damaged	528.70 FL	*- FL
18	1		*FRONT KNUCKLE ARM RH	Not Damaged	499.80 FL	*- FL
19	1		*FRONT KNUCKLE ARM BEARING RH	Not Damaged	341.50 FL	*- FL
20	1		*FRONT LOWER ARM RH	Not Damaged	378.50 FL	*- FL
21	1		*FRONT LOWER ARM BALL JOINT RH	Not Damaged	219.70 FL	*- FL
22	1		*FRONT UPPER ARM RH	Not Damaged	479.80 FL	*- FL
23	1		*FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
24	1		*FRONT WHEEL RIM RH	Not Damaged	250.00 FS	*- FS
25	1		*FRONT WHEEL TYRE RH	Not Damaged	350.00 FS	*- FS
26	1		*FRONT DOOR STEP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (\$)	14,537.90	2,868.60
					- List Item Discount on L Items 10.00/10.00% (\$)	1,378.79	283.86
					Total Parts (\$)	13,159.11	2,584.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	0.00
2	TO TRANSFER FRONT DOOR COMPONENT FROM OLD TO NEW	New	350.00	200.00
3	TO REMOVE ,REFIT AND TEST UNDERCARRIAGE ITEMS	New	300.00	0.00
4	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	200.00	0.00
5	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	1,000.00	600.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,950.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >