

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008132/R1BS3Q2
Date: 05/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLT8211H	Insured Vehicle No :	SMH704G
Date of Loss:	02/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT8211H		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGHH685428
Reg. Date:	14/11/2017 (Man. Year: 2017)	Chassis No:	KNAFX411MJ5751953
Colour:	Black	Odometer:	76282 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,520.00	3,685.00	3,835.00	51.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,840.00	4,980.00	2,860.00	36.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,360.00	8,665.00	6,695.00	43.59
+ GST 7.00/7.00% (S\$)	1,075.20	606.55	468.65	43.59

Nett Amount (S\$)	16,435.20	9,271.55	7,163.65	43.59
+ Car Rental (11.0 x S\$120.00/day + 7.00% GST) (S\$)		1,412.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,691.40		

INSPECTION

Date of Assignment: 02/08/2021

Date Inspected: 05/08/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8211H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*PARKING SENSOR	Not Necessary	280.00 FS	*- FS
3	1		*COVER -RR BUMPER	Deformed	688.00 FS	*688.00 FS
4	1		*COVER -RR BUMPER ,CTR	Deformed	315.00 FS	*315.00 FS
5	2		*BRACKET -RR BEAM LWR MTG	Not Necessary	10.00 FS	*- FS
6	1		*BRACKET -RR BEAM LWR CTR	Not Necessary	5.00 FS	*- FS
7	1		*BEAM -RR BUMPER	Cracked	318.00 FS	*318.00 FS
8	1		*BRACKET -RR BEAM UPR MTG ,RH	Not Necessary	3.00 FS	*- FS
9	1		*BRACKET -RR BEAM UPR MTG	Not Necessary	3.00 FS	*- FS
10	1		*STAY -RR BUMPER RH	Bent	120.00 FS	*120.00 FS
11	1		*STAY -RR BUMPER LH	Bent	120.00 FS	*120.00 FS
12	1		*BRACKET ,RR BUMPER SIDE MTG ,RH	Not Necessary	29.00 FS	*- FS
13	1		*BRACKET ,RR BUMPER SIDE MTG ,LH	Not Necessary	29.00 FS	*- FS
14	1		*PANEL ASSY -TRUNK LID	Bent	1,570.00 FS	*1,570.00 FS
15	1		*HINGE ASSY -TRUNK LID,RH	Serviceable	68.00 FS	*- FS
16	1		*HINGE ASSY -TRUNK LID,LH	Serviceable	68.00 FS	*- FS
17	1		*PANEL ASSY -BACK	Bent	324.00 FS	*324.00 FS
18	1		*LATCH ASSY -TRUNK LID	Serviceable	112.00 FS	*- FS
19	1		*TRIM T/LID	Serviceable	82.00 FS	*- FS
20	1		*W/STRIP -TRUNK LID OPNG	Not Necessary	100.00 FS	*- FS
21	1		*LOGO ASSY -KIA SUB	Necessary	37.00 FS	*37.00 FS
22	1		*EMBLEM -CERATO	Necessary	35.00 FS	*35.00 FS
23	1		*TRIM -TRANSVERSE RR	Deformed	58.00 FS	*58.00 FS
24	1		*LAMP ASSY -REAR COMB INSIDE ,RH	Not Necessary	710.00 FS	*- FS
25	1		*LAMP ASSY -REAR COMB INSIDE ,LH	Not Necessary	710.00 FS	*- FS
26	1		*LAMP ASSY -REAR COMBINATION ,RH	Not Necessary	788.00 FS	*- FS
27	1		*LAMP ASSY -REAR COMBINATION ,LH	Not Necessary	788.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	10		*CLIPS	Necessary	20.00 FS	*20.00 FS
29	5		*FASTENER	Necessary	5.00 FS	*5.00 FS
30	1		*EMBLEM K3	Necessary	15.00 FS	*15.00 FS
31	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
32	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
					Total Parts (\$\$)	7,520.00 3,685.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW REAR BUMPER ,BOOTLID ,REAR END PANEL ,REPAIR REAR COMPARTMENT REAR FENDER RH & LH	New	3,200.00	2,560.00
2	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
3	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	300.00	300.00
4	SPRAY PAINT FOR REAR BUMPER ,BOOTLID ,REAR END PANEL ,REAR COMPARTMENT REAR FENDER RH & LH	New	3,850.00	1,650.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	80.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM	New	280.00	280.00
Gross Labour Cost (S\$)			7,840.00	4,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >