



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
 PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Chan Fann Howe	Cust No/Name	LCV01751/Chan Fann Howe
Blk 492C Tampines St 45	Reg No/Reg Date	SLT8211H / 14/11/201
#05-288	Date In/Mileage	/ 0
Singapore 522492	Chassis No	KNAFX411MJ5751953
Contact No	Engine No	G4FGHH685428
	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV01751	CRDVCH	02/08/2021/ 10:22	TLC	442 / CocoLu	37150

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

E PNT88000				3200.00
RENEW REAR BUMPER, BOOTLID, REAR END PANEL. REPAIR REAR COMPARTMENT @ 640 x 4				2560
REAR FENDER RH & LH				80
E PNT88000				100.00
REMOVE & INSTALL PARKING SENSOR				300.00
E PNT88000				300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS				1650
E PNT98000				3850.00
SPRAY PIAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL. REAR COMPARTMENT @ 550 x 3				
REAR FENDER RH & LH				
M SUNDRY				40.00
C&C LOGO				
M SUNDRY				80.00
APPLY SEALANT FOR ACCIDENT PORTION				X 50.00
M SUNDRY				
REAR NUMBER PLATE WITH FRAME				30.00
A 90000001				280.00
CHECK WIRING & ELECTRICAL SYSTEM				
A 10028901				20.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				
M SUNDRY				280.00
Sundry				
M SUNDRY				
SUPPLY PARKING SENSOR				
M COVER-RR BUMPER de	1.00	688.00	00.00	688.00
M COVER-RR BUMPER,CTR de	1.00	315.00	00.00	315.00
P BRACKET-RR BEAM LWR MTG ?	2.00	5.00	00.00	10.00
M BRACKET-RR BEAM LWR,CTR ?	1.00	5.00	00.00	5.00
M BEAM-RR BUMPER ?	1.00	318.00	00.00	318.00
M BRACKET-RR BEAM UPR MTG, RH ?	1.00	3.00	00.00	3.00
M BRACKET-RR BEAM UPR MTG ?	1.00	3.00	00.00	3.00
M STAY-RR BUMPER RH ?	1.00	120.00	00.00	120.00
M STAY-RR BUMPER LH ?	1.00	120.00	00.00	120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Chan Fann Howe	Cust No/Name LCV01751/Chan Fann Howe
Blk 492C Tampines St 45	Reg No/Reg Date SLT8211H / 14/11/201
#05-288	Date In/Mileage / 0
Singapore 522492	Chassis No KNAFX411MJ5751953
Contact No	Engine No G4FGHH685428
	Make/Model KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV01751	CRDVCH	02/08/2021/ 10:22	TLC	442 / CocoLu	37150
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-RR BUMPER SIDE MTG,RH ?		1.00	29.00	00.00	29.00
M BRACKET-RR BUMPER SIDE MTG,LH ?		1.00	29.00	00.00	29.00
M PANEL ASSY-TRUNK LID <i>bt</i>		1.00	1570.00	00.00	1570.00
M HINGE ASSY-TRUNK LID,RH X		1.00	68.00	00.00	68.00
M HINGE ASSY-TRUNK LID,LH X		1.00	68.00	00.00	68.00
M PANEL ASSY-BACK <i>bt - photo?</i>		1.00	324.00	00.00	324.00
M LATCH ASSY-TRUNK LID <i>EX</i>		1.00	112.00	00.00	112.00
M TRIM T/LID X		1.00	82.00	00.00	82.00
M W/STRIP-TRUNK LID OPNG ?		1.00	100.00	00.00	100.00
M LOGO ASSY-KIA SUB <i>re</i>		1.00	37.00	00.00	37.00
M EMBLEM-CERATO <i>re</i>		1.00	35.00	00.00	35.00
M TRIM-TRANSVERSE RR <i>de</i>		1.00	58.00	00.00	58.00
M LAMP ASSY-REAR COMB INSIDE,RH <i>i</i>		1.00	710.00	00.00	710.00
M LAMP ASSY-REAR COMB INSIDE,LH <i>i</i>		1.00	710.00	00.00	710.00
M LAMP ASSY-REAR COMBINATION,RH X		1.00	788.00	00.00	788.00
M LAMP ASSY-REAR COMBINATION,LH ?		1.00	788.00	00.00	788.00

SURVEYOR NAME: Pau - 4p 90010068SURVEYOR SIGNATURE: PauDATE: 05/08/21 @ 120

REMARKS:

8 daysRes before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on **Nett 15,320.00**
1072.40

Total Payable 16,392.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.