

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008135/EPA3Q2**Date:** 03/12/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBS2519J**Insured Vehicle No :** SKX4505C

Date of Loss: 15/07/2021

Nature of Claim: TP

Claim No: 9640477280SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBS2519J**

Make & Model: YAMAHA VIXION R, 155cc

Engine No: G3J6E0226120

Reg. Date: 01/03/2021 (Man. Year: 2020)

Chassis No: MH3RG4810KK033873

Colour: Grey

Odometer: 5371 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80 -17

Rear Tyre Size: 130/70-11

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,339.20	1,018.80	320.40	23.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	740.00	610.00	130.00	17.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,079.20	1,628.80	450.40	21.66
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,079.20	1,300.00	779.20	37.48
+ GST 7.00/7.00% (S\$)	145.54	91.00	54.54	37.47
Nett Amount (S\$)	2,224.74	1,391.00	833.74	37.48
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
(S\$)		1,491.00		
Liabe Amount (50.00%) (S\$)		745.50		
Global Sum Settlement (S\$)		750.00		

INSPECTION

Date of Assignment: 02/08/2021

Date Inspected: 02/08/2021 Inspected At:

Southern Motor (HQ)

BLK 1006 BUKIT MERAH LANE 2, #01-10

Singapore 159762

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Broken	95.00 FL	*78.00 FL
2	1		*FRONT BRAKE DISK	Not Necessary	185.00 FL	*- FL
3	1		*HANDLE BAR	Bent	65.00 FL	*65.00 FL
4	1		*CLUTCH LEVER	Broken	25.00 FL	*25.00 FL
5	1		*HANDLE BALANCER	Cut	25.00 FL	*25.00 FL
6	1		*FRONT SIGNAL LIGHT	Broken	65.00 FL	*65.00 FL
7	1		*FRONT FAIRING	Cut	225.00 FL	*168.00 FL
8	1		*FUEL TANK COVER	Cut	385.00 FL	*288.00 FL
9	1		*GEAR LEVER	Broken	90.00 FL	*90.00 FL
10	1		*FRONT FOOTREST	Bent	45.00 FL	*45.00 FL
11	1		*SIDE STAND	Bent	58.00 FL	*58.00 FL
12	1		*SET REAR FOOTREST	Broken	65.00 FL	*65.00 FL
13	1		*EXHAUST PIPE COVER	Cut	160.00 FL	*160.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,488.00	1,132.00
- List Item Discount on L Items 10.00/10.00% (\$)	148.80	113.20
Total Parts (\$)	1,339.20	1,018.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	30.00	30.00
2	ALIGNMENT FORK	New	95.00	50.00
3	ALIGNMENT FORK RIM	New	65.00	50.00
4	JACK REAR BODY	New	120.00	100.00
5	REAR GIVI BOX	New	180.00	180.00
6	LABOR	New	250.00	200.00
Gross Labour Cost (\$\$)			740.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >