

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008136/T1TF3E2

Date: 14/01/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001463003

Claimant Vehicle No : SGY1704G

Insured Vehicle No : XD1864L

Date of Loss: 30/07/2021

Nature of Claim: TP

Claim No: 260671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY1704G**

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)

Engine No: 4A910054747

Reg. Date: 19/09/2007 (Man. Year: 2007)

Chassis No: JMYSRCY2A8U001354

Colour: Black

Odometer: 226896 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,844.20	3,754.15	17,090.05	81.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	1,610.00	4,790.00	74.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,244.20	5,364.15	21,880.05	80.31
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	27,244.20	3,900.00	23,344.20	85.69
+ GST 7.00/7.00% (S\$)	1,907.09	273.00	1,634.09	85.68
Nett Amount (S\$)	29,151.29	4,173.00	24,978.29	85.69

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 04/08/2021 Inspected At:

AP Automotive Services Pte Ltd
56 Loyang Way, #04-04 Loyang Enterprise
Building
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2021)

Parts: 143 MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGY1704G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,339.00 FL	*557.00 FL
2	2		*BOOTLID LAMP L+R	Not Necessary	446.00 FL	*- FL
3	1		*BOOTLID CENTER LAMP	Not Necessary	160.00 FL	*- FL
4	1		*BOOTLID LOGO	Necessary	67.00 FL	*67.00 FL
5	1		*BOOTLID EMBLEM - LANCER	Necessary	97.00 FL	*97.00 FL
6	1		*BOOTLID EMBLEM - EX	Necessary	52.00 FL	*52.00 FL
7	1		*BOOTLID EMBLEM - C&C	Necessary	32.00 FL	*32.00 FL
8	1		*BOOTLID LOCK	Bent	194.00 FL	*194.00 FL
9	1		*BOOTLID LOCK CATCH	Not Necessary	90.00 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Cut	215.00 FL	*166.50 FL
11	2		*TAIL LAMP L+R	Cracked	770.00 FL	*770.00 FL
12	2		*TAIL LAMP PANEL L+R	Not Necessary	340.00 FL	*- FL
13	1		*REAR BUMPER	Deformed	1,205.00 FL	*731.00 FL
14	2		*REAR BUMPER REFLECTOR L+R	Cracked	20.00 FL	*20.00 FL
15	2		*REAR BUMPER RETAINER L+R	Necessary	258.00 FL	*80.00 FL
16	1		*REAR BUMPER REINFORCEMENT BAR	Bent	482.00 FL	*169.00 FL
17	1		*REAR BUMPER SPONGE	Not Necessary	131.00 FL	*- FL
18	1		*REAR WINDSCREEN MOULDING	Not Necessary	149.00 FL	*- FL
19	2		*REAR FENDER L+R	Not Necessary	2,188.00 FL	*- FL
20	2		*REAR FENDER INNER TRIM L+R	Not Necessary	830.00 FL	*- FL
21	2		*REAR FENDER COWLING L+R	Torn	134.00 FL	*134.00 FL
22	1		*END PANEL	Bent	699.00 FL	*407.00 FL
23	1		*END PANEL TOP GARNISH	Deformed	182.00 FL	*140.00 FL
24	1		*SPAREWHEEL PANEL	Repair	983.00 FL	*- FL
25	1		*SPAREWHEEL PANEL TOP BOARD	Deformed	238.00 FL	*127.00 FL
26	1		*EXHAUST PIPE	Not Necessary	961.00 FL	*- FL
27	1		*EXHAUST HEAT SHIELD	Not Necessary	376.00 FL	*- FL
28	1		*BOOTLID SPOILER	Not Necessary	4,000.00 FS	*- FS
29	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
30	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
31	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
32	1		*REAR BUMPER	Not Necessary	3,500.00 FS	*- FS
33	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
34	1		*SET REAR BUMPER REVERSE SENSOR	Necessary	300.00 FS	*200.00 FS
35	1		*REAR NUMBER PLATE	Bent	250.00 FS	*45.00 FS
36	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
37	2		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
38	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
39	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
40	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,108.00	4,128.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,263.80	374.35
Total Parts (\$\$)	20,844.20	3,754.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	700.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
5	TO CHECK WIRING AND BOOTLID LAMP FUNCTION	New	150.00	0.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR REAR BOOT MECHANISM	New	350.00	60.00
9	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
10	TO PERFORM RUST PROOFING	New	400.00	30.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
Gross Labour Cost (\$\$)			6,400.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >