

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG21008137/BUF3N2**Date:** 01/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001428568
<b>Claimant Vehicle No :</b>	GBL201A	<b>Insured Vehicle No :</b>	SMM4025E
Date of Loss:	24/07/2021	Nature of Claim:	TP
		Claim No:	260706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL201A	Engine No:	1KDB066081
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)	Chassis No:	JTFHT02P200251064
Reg. Date:	24/02/2021 (Man. Year: 2020)	Odometer:	18272 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,021.12	3,447.25	1,573.87	31.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,490.00	1,490.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,001.12</b>	<b>4,937.25</b>	<b>3,063.87</b>	<b>38.29</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	8,001.12	3,600.00	4,401.12	55.01
<b>+ GST 7.00/7.00% (S\$)</b>	560.08	252.00	308.08	55.01
<b>Nett Amount (S\$)</b>	<b>8,561.20</b>	<b>3,852.00</b>	<b>4,709.20</b>	<b>55.01</b>

INSPECTION

Date of Assignment:	02/08/2021	
Date Inspected:	04/08/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

**Adjuster:** Lim Teow Guan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Oct 2021)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL201A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,032.50 FL	*1,755.90 FL
2	1		*TAILGATE CENTRE EMBLEM	Necessary	71.60 FL	*71.60 FL
3	1		*TAILGATE LOCK	Jammed	263.00 FL	*263.00 FL
4	1		*TAILGATE LOCK CATCH	Not Damaged	70.20 FL	*- FL
5	1		*REAR BUMPER	Dented	454.30 FL	*374.45 FL
6	4		*REAR BUMPER LOWER BRACKETS	No such part	180.40 FL	*- FL
7	1		*REAR BUMPER RH SIDE RETAINER	Necessary	66.10 FL	*33.40 FL
8	1		*REAR BUMPER LH SIDE RETAINER	Necessary	66.10 FL	*33.40 FL
9	1		*RH TAILLAMP ASSY	Broken	354.80 FL	*354.80 FL
10	1		*RH TAILLAMP LOWER COVER	No such part	157.00 FL	*- FL
11	1		*RH TAILLAMP LOWER COVER RETAINER	No such part	53.00 FL	*- FL
12	1		*END PANEL (OUTER)	Dented	563.00 FL	*563.00 FL
13	1		*END PANEL TOP MOULDING	No such part	198.10 FL	*- FL
14	1		*END PANEL RH SIDE PANEL	Broken	336.10 FL	*231.35 FL
15	1		*EXHAUST PIPE	Dented	980.20 FL	*467.00 FL
16	1		*EXHAUST PIPE GASKET	Necessary	35.10 FL	*35.10 FL
17	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*30.00 FS
18	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*30.00 FS
19	1		*TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*20.00 FS
20	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
21	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
22	1		*SET REAR BUMPER REVERSE SENSORS	Short Circuit	320.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,491.50</b>	<b>4,493.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,470.38	1,045.75
<b>Total Parts (\$\$)</b>	<b>5,021.12</b>	<b>3,447.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	80.00	0.00
5	REMOVE,REPLACE AND REINSTALL TAILGATE WINDSCREEN GLASS AND SEALANTS TO ASSIST REPAIR	New	220.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER PARTS TO NEW TAILGATE	New	100.00	60.00
7	REMOVE AND REINSTALL REAR INNER TRIM AND BOARDS TO ASSIST REPAIR	New	280.00	0.00
8	REMOVE,REPLACE AND ADJUST REAR BUMPER REVERSE SENSOR TO ASSIST REPAIR	New	100.00	60.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	120.00	50.00
<b>Gross Labour Cost (\$)</b>			<b>2,980.00</b>	<b>1,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >