

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21008138/Etce2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	11/08/2021	
	ATTN: KHOR SAW	/ THENG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	FBR 310L	Veh. Inspected		FBR 9113E	
	Policy No.	P2384534	Coverage (\$)		0.00	
	Claim No.	S1M03EMG	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		02/08/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA R15	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	ME1RG6719L0045485	Colour		BLACK	
	Odometer	7784 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80-17	DUNLOP		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70 R17	DUNLOP		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
5.	General Information					
	Accident Date	29/07/2021	Inspect Date /	Time	03/08/2021 (10:00 AM)	
	Survey held at	34 Toh Guan Road East #01-29	Singapore 608579			
	Repairer	M 1 MOTORING				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/ASM21008138/Etce2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser