

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008139/AGA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKC9072L**Insured Vehicle No :** ER8183Z

Date of Loss: 28/07/2021

Nature of Claim: TP Claim No: 1955239142SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKC9072L**

Make & Model: CHEVROLET CRUZE, 1.6 2WD (A)

Engine No: F16D4286177KA

Reg. Date: 13/10/2011 (Man. Year: 2011)

Chassis No: KL1JA69E9CK558608

Colour: Black

Odometer: 87905 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,325.74	1,678.70	2,647.04	61.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,060.00	1,310.00	55.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,695.74	2,738.70	3,957.04	59.10
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	6,695.74	1,200.00	5,495.74	82.08
+ GST 7.00/7.00% (S\$)	468.70	84.00	384.70	82.08
Nett Amount (S\$)	7,164.44	1,284.00	5,880.44	82.08
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,591.45		
Global Sum Settlement (S\$)		1,590.00		

INSPECTION

Date of Assignment: 30/07/2021

Date Inspected: 30/07/2021 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,120.20 FL	*1,120.20 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	72.50 FL	*72.50 FL
3	1		*FRONT FENDER RH	Dented	650.30 FL	*650.30 FL
4	1		*FRONT FENDER SIGNAL LAMP LH	Not Necessary	60.20 FL	*- FL
5	1		*FRONT FENDER INNER COWLING LH	Not Necessary	170.20 FL	*- FL
6	1		*HEADLAMP RH	Not Necessary	1,355.20 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
8	1		*FRONT BUMPER LOWER LID	Repair	1,200.00 FS	*- FS
9	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					4,668.60	1,863.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					342.86	184.30
Total Parts (\$\$)					4,325.74	1,678.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	600.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	120.00	30.00
Gross Labour Cost (\$\$)			2,370.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >