

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG17020484/KPA3Q2-1**Date:** 10/02/2022**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SLK130H **Insured Vehicle No :** SJQ9382E

Date of Loss: 12/10/2017 Nature of Claim: TP Claim No: 3941753711SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLK130H**

Make & Model: BMW 520I, 2.0 (A) Engine No: HIDDEN

Reg. Date: 01/10/2009 (Man. Year: 2009) Chassis No: WBANT120X0CX30526

Colour: Metallic Dark Blue Odometer: 160625 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18

Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm

Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,780.00	10,718.52	9,061.48	45.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	2,410.00	1,580.00	39.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,770.00</b>	<b>13,128.52</b>	<b>10,641.48</b>	<b>44.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>10,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>23,770.00</b>	<b>10,450.00</b>	<b>13,320.00</b>	<b>56.04</b>
<b>+ Loss of Use (9.0 x S\$100.00/day) (S\$)</b>		900.00		
<b>+ Doc/Search Fee (S\$)</b>		5.35		
<b>Nett Liability (S\$)</b>		<b>11,355.35</b>		
<b>Global Sum Settlement (S\$)</b>		<b>11,300.00</b>		

**INSPECTION**

Date of Assignment: 25/10/2017

Date Inspected: 25/10/2017 Inspected At: Autoworx House - Sin Ming (HQ)  
176 SIN MING DRIVE #02-01  
Singapore 575721

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,700.00 FL	*1,380.00 FL
2	1		*REAR BOOT EMBLEM LOGO	Serviceable	72.30 FL	*- FL
3	1		*REAR BOOT OPEN LATCH	Serviceable	196.60 FL	*- FL
4	1		*REAR BOOT NUMBER PLATE LAMP	Serviceable	50.00 FL	*- FL
5	1		*REAR BOOT OUTER GARNISH	Serviceable	399.60 FL	*- FL
6	1		*REAR BOOT LOCK	Repair	167.40 FL	*- FL
7	1		*REAR BOOT LOCK CATCH	Repair	83.70 FL	*- FL
8	1		*REAR BUMPER (M-TECH VERSION)	Buckled	2,780.00 FL	*1,950.00 FL
9	1		*REAR BUMPER CLIPS (25 PCS)	Necessary	120.00 FS	*60.00 FS
10	2		*REAR BUMPER BRACKET	Repair	120.00 FL	*- FL
11	2		*REAR BUMPER SIDE BRACKET	Serviceable	200.00 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Buckled	720.00 FL	*650.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKETS	Bent	694.74 FL	*340.00 FL
14	1		*REAR BUMPER INNER PAD	Cracked	289.00 FL	*289.00 FL
15	1		*REAR BUMPER LOWER KIT	Bent	855.00 FL	*605.00 FL
16	1		*REAR BUMPER SPONGE	No such part	367.00 FL	*- FL
17	1		*REAR BUMPER TOP GARNISH	Serviceable	283.00 FL	*- FL
18	1		*REAR BUMPER TOW COVER	Serviceable	84.00 FL	*- FL
19	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Dented(2Pcs Only)	1,136.00 FL	*528.00 FL
20	4		*REAR BUMPER REVERSE SENSOR GARNISH	Serviceable	340.00 FL	*- FL
21	1		*REAR END PANEL	Bent	844.00 FL	*844.00 FL
22	1		*REAR END PANEL GARNISH	Mtg Cracked	680.00 FL	*168.60 FL
23	1		*REAR EXHAUST SILENCER	Bent	2,300.00 FL	*1,180.00 FL
24	2		*REAR EXHAUST SILENCER RUBBER MOUNT	Serviceable	108.00 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD	Repair	374.00 FL	*- FL
26	2		*REAR TAIL LAMP ASSY	Cut	1,720.00 FL	*1,042.60 FL
27	2		*FRONT SEAT HEAD REST	Activated	3,304.00 FL	*1,520.00 FL
28	1		*FRONT SEAT HEAD REST CHARGER	Necessary	316.50 FL	*316.50 FL
29	1		*PDC CONTROL UNIT	Necessary	465.00 FL	*465.00 FL
30	1		*REAR END PANEL CENTRE DUST COVER	Serviceable	299.60 FL	*- FL
31	1		*REAR END PANEL RH DUST COVER	Missing	278.00 FL	*278.00 FL
32	1		*SPARE TYRE/TOOLS FOAM BOX	Deformed	415.00 FL	*286.10 FL
33	1		*SPARE TYRE/TOOLS FOAM COVER	Serviceable	202.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,964.44</b>	<b>11,902.80</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	2,184.44	1,184.28

<b>Total Parts (\$\$)</b>	<b>19,780.00</b>	<b>10,718.52</b>
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	1,000.00
2	TO CHECK WIRING SYSTEM AND RESET ECU	New	100.00	20.00
3	TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	900.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
5	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS	New	150.00	30.00
6	TO INSTALL REVERSE SENSOR AND RESET ECU PROGRAMME	New	300.00	120.00
7	TO REMOVE CARPET & TRIMMING TO ENABLE REPAIR	New	120.00	80.00
8	TO CARRY OUT EXHAUST WORKS	New	150.00	80.00
9	TO RESET SRS SYSTEM	New	220.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,990.00</b>	<b>2,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >