

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008144/ETF3E2

Date: 10/11/2021

REFERENCE

Insured/Claimant:	MEE SOOK HONG CIUPA	Policy No:	1900161517	
Date of Loss:	01/08/2021	Nature of Claim:	OD	Claim No: 3887347077SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW6663H	Engine No:	G4FGKH749527
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF5416MK5052935
Reg. Date:	18/09/2019 (Man. Year: 2019)	Odometer:	21071 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$84,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,282.00	4,693.60	3,588.40	43.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,880.00	6,330.00	2,550.00	28.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,162.00	11,023.60	6,138.40	35.77
+ GST 7.00/7.00% (S\$)	1,201.34	771.65	429.69	35.77
Nett Amount (S\$)	18,363.34	11,795.25	6,568.09	35.77

INSPECTION

Date of Assignment:	03/08/2021	
Date Inspected:	03/08/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-PILLAR OUTER, LH	Dented	2,345.00 FL	*2,345.00 FL
2	1		*PANEL-ROOF	Dented	843.00 FL	*843.00 FL
3	1		*RING ASSY-SUNROOF REINF	Not Necessary	406.00 FL	*- FL
4	1		*RAIL ASSY-ROOF FR	Not Necessary	112.00 FL	*- FL
5	1		*HEADLINING ASSY	Crushed	1,584.00 FL	*1,584.00 FL
6	1		*SUNROOF ASSY	Not Necessary	3,172.00 FL	*- FL
7	1		*MOULDING ASSY-FRT DR FRAME, LH	Not Necessary	72.00 FL	*- FL
8	1		*W/STRIP ASSY-FR DR BELT O/S LH	Not Necessary	80.00 FL	*- FL
9	1		*MOULDING ASSY-RR DR FRAME, LH	Not Necessary	50.00 FL	*- FL
10	1		*W/STRIP ASSY-RR DR BELT O/S LH	Not Necessary	75.00 FL	*- FL
11	1		*BLACK TAPE-RR DR FRAME RR OTR	Not Necessary	8.00 FL	*- FL
12	1		*MOULDING ASSY-ROOF, LH	Cut	43.00 FL	*43.00 FL
13	1		*GLASS-WINDSHIELD	Broken	821.00 FL	*821.00 FL
14	1		*MOULDING-WINDSHIELD GLASS	Necessary	56.00 FL	*56.00 FL
15	1		*GLASS ASSY-REAR WINDOW	Not Necessary	447.00 FL	*- FL
16	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
17	1		*BLACK TAPE-FR DR RR, LH	Not Necessary	13.00 FL	*- FL
18	1		*BLACK TAPE-FR DR FR, LH	Not Necessary	13.00 FL	*- FL
19	1		*W/STRIP ASSY-FR DR SIDE LH	Cut	102.00 FL	*102.00 FL
			(Supplementary)			
20	1		*STOPPER-GLASS(X2)	Necessary	8.00 FL	*8.00 FL
			(Supplementary)			
21	1		*PAD-WINDSHIELD GLASS (X20)	Necessary	40.00 FL	*40.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,340.00	5,862.00
- List Item Discount on L Items 20.00/20.00% (S\$)	2,058.00	1,168.40
Total Parts (S\$)	8,282.00	4,693.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE ROOF PANEL, LH BODY FRAME & AFFECTED AREA	New	4,000.00	2,400.00
2	PAINT WORK ON ROOF PANEL & LH SIDE FRAME PANEL	New	1,050.00	700.00
3	REPLACE FRT WINDSCREEN GLASS	New	240.00	240.00
4	TO APPLY FRT WINDSCREEN SEALANT	New	80.00	80.00
5	TO SUPPLY FRT WINDSCREEN SOLAR FILM	New	220.00	220.00
6	REMOVE & INSTALL ROOF GLASS FOR FACILITATE REPAIR	New	300.00	300.00
7	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
8	TO APPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
9	REPLACE ROOF LINING	New	400.00	400.00
10	REMOVE & INSTALL DASHBOARD FOR FACILITATE REPAIR	New	400.00	400.00
11	REMOVE & INSTALL FRT SEAT AND CARPET FOR FACILITATE REPAIR	New	200.00	200.00
12	REMOVE & INSTALL REAR SEAT AND CARPET FOR FACILITATE REPAIR	New	200.00	200.00
13	REMOVE & INSTALL LH B PILLAR FOR FACILITATE REPAIR	New	200.00	120.00
14	REMOVE & INSTALL LH FRT & REAR DOOR FOR FACILITATE REPAIR	New	400.00	200.00
15	TO CLEAN & VACUUM FRT SHATTERED GLASS	New	120.00	80.00
16	REMOVE & INSTALL ALL PILLAR TRIMS FOR FACILITATE REPAIR	New	240.00	80.00
17	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
18	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
19	TO APPLY BODY SEALANT ON AFFECTED AREA	New	160.00	80.00
20	PERFORM RUST PREVENTION	New	80.00	40.00
21	SUPPLY & INSTALL SUN ROOF SOLAR FILM - RIKECOOL (Supplementary)	New	120.00	120.00
Gross Labour Cost (\$\$)			8,880.00	6,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >