

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11148/MEE SOOK HONG CIUPA
	Reg No/Reg Date	SJW6663H / 18/09/201
	Date In/Mileage	02/08/2021/ 0
	Chassis No	KNAF5416MK5052935
	Engine No	G4FGKH749527
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	03/08/2021/ 09:52	QUK	282 / Kevin Leong	37209			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								4000.00
REPLACE ROOF PANEL, LH BODY FRAME & AFFECTED AREA								
E PNT98000								1050.00
PAINT WORK ON ROOF PANEL & LH SIDE FRAME PANEL								
E PNT88000								240.00
REPLACE FRT WINDSCREEN GLASS								
M SUNDRY								80.00
TO APPLY FRT WINDSCREEN SEALANT								
M SUNDRY								220.00
TO SUPPLY FRT WINDSCREEN SOLAR FILM								
E PNT88000								300.00
REMOVE & INSTALL ROOF GLASS FOR FACILITATE REPAIR								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO APPLY REAR WINDSCREEN SEALANT								
E PNT88000								400.00
REPLACE ROOF LINING								
A 52900099								400.00
REMOVE & INSTALL DASHBOARD FOR FACILITATE REPAIR								
E PNT88000								200.00
REMOVE & INSTALL FRT SEAT AND CARPET FOR FACILITATE REPAIR								
E PNT88000								200.00
REMOVE & INSTALL REAR SEAT AND CARPET FOR FACILITATE REPAIR								
E PNT88000								200.00
REMOVE & INSTALL LH 'B' PILLAR FOR FACILITATE REPAIR								
E PNT88000								400.00
REMOVE & INSTALL LH FRT & REAR DOOR FOR FACILITATE REPAIR								
E PNT88000								120.00
TO CLEAN & VACUUM FRT SHATTERED GLASS								
E PNT88000								240.00
REMOVE & INSTALL ALL PILLAR TRIMS FOR FACILITATE REPAIR								
A 54900099								30.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11148/MEE SOOK HONG CIUPA
	Reg No/Reg Date	SJW6663H / 18/09/201
	Date In/Mileage	02/08/2021/ 0
	Chassis No	KNAF5416MK5052935
	Engine No	G4FGKH749527
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	03/08/2021/ 09:52	QUK	282 / Kevin Leong	37209			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								160.00
TO APPLY BODY SEALANT ON AFFECTED AREA								
M SUNDRY								80.00
PERFORM RUST PREVENTION								
M SUNDRY								50.00
SUNDRIES								
M PANEL ASSY-PILLAR OUTER,LH					1.00	2345.00	20.00	1876.00
M PANEL-ROOF					1.00	843.00	20.00	674.40
M RING ASSY-SUNROOF REINF					1.00	406.00	20.00	324.80
M RAIL ASSY-ROOF FR					1.00	112.00	20.00	89.60
M HEADLINING ASSY					1.00	1584.00	20.00	1267.20
M SUNROOF ASSY					1.00	3172.00	20.00	2537.60
M MOULDING ASSY-FRT DR FRAME,LH					1.00	72.00	20.00	57.60
M W/STRIP ASSY-FR DR BELT O/S LH					1.00	80.00	20.00	64.00
M MOULDING ASSY-RR DR FRAME,LH					1.00	50.00	20.00	40.00
M W/STRIP ASSY-RR DR BELT O/S LH					1.00	75.00	20.00	60.00
M BLACK TAPE-FR DR RR,LH					1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FR,LH					1.00	13.00	20.00	10.40
M BLACK TAPE-RR DR FRAME RR OTR,					1.00	8.00	20.00	6.40
M MOULDING ASSY-ROOF,LH					1.00	43.00	20.00	34.40
M GLASS-WINDSHIELD					1.00	821.00	20.00	656.80
M MOULDING-WINDSHIELD GLASS					1.00	56.00	20.00	44.80
M GLASS ASSY-REAR WINDOW					1.00	447.00	20.00	357.60

Confirm & accepted by

Nett	16,922.00
7% GST on	16922.00
Total Payable	18,106.54

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.