



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 7268U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	595.00	595.00
2	REAR BUMPER SIDE @\$305.00	N/S DEFORMED	610.00	305.00
2	REAR BUMPER HOLDER @\$35.00	NECESSARY	70.00	70.00
2	REAR BUMPER REFLECTOR @\$42.00	N/S CRACKED	84.00	42.00
1	REAR BUMPER REINFORCEMENT	DENTED	520.00	520.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	855.00	-
1	TAILLAMP LOWER COVER LH	CRACKED	270.00	270.00
	LESS 10% DISCOUNT		-	-180.20
			3,004.00	1,621.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	220.00
			310.00	250.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	300.00
	SPRAY PAINTING.		400.00	300.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,150.00	680.00
	<b>GRAND TOTAL</b>		<b>4,464.00</b>	<b>2,551.80</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,050.00</b>
---	--	--	-----------------

Report Ref No. CS/TP21008147/Avce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.