

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21008148/AQCN2**Date:** 01/10/2021**REFERENCE**

Insured/Claimant:	ABHISHEK GARG	Policy No:	1900171616-01	
Date of Loss:	25/07/2021	Nature of Claim:	OD	Claim No: 3896024817SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMP5817P</b>		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX058089
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZFVYXK2123257
Colour:	White	Odometer:	13066 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,381.00	5,041.68	10,339.32	67.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,672.00	4,872.00	13,800.00	73.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,053.00</b>	<b>9,913.68</b>	<b>24,139.32</b>	<b>70.89</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>33,053.00</b>	<b>8,913.68</b>	<b>24,139.32</b>	<b>73.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,313.71</b>	<b>623.96</b>	<b>1,689.75</b>	<b>73.03</b>
<b>Nett Amount (S\$)</b>	<b>35,366.71</b>	<b>9,537.64</b>	<b>25,829.07</b>	<b>73.03</b>

**INSPECTION**

Date of Assignment:	03/08/2021		
Date Inspected:	02/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	84.00 FS	*- FS
2	1		*REAR WHEEL ARCH COVER-LH/RH	Necessary	1,166.00 FS	*932.80 FS
3	1		*REAR FENDER-LH	Repair	4,902.00 FS	*- FS
4	1		*REAR SIDE WINDOW-LH	Not Necessary	832.00 FS	*- FS
5	1		*REAR SIDE WINDOW PRIMER	Not Necessary	20.00 FS	*- FS
6	1		*REAR DOOR-LH	Dented	4,085.00 FS	*3,268.00 FS
7	1		*REAR DOOR SEAL-LH	Necessary	205.00 FS	*164.00 FS
8	1		*REAR DOOR BONDING AGENT	Not Necessary	49.00 FS	*- FS
9	1		*REAR DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
10	1		*REAR DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
11	1		*SEALING STRIP	Not Necessary	17.00 FS	*- FS
12	1		*GROMMET	Not Necessary	9.00 FS	*- FS
13	1		*REAR DOOR CATCH-LH	Damaged	146.00 FS	*116.40 FS
14	1		*REAR DOOR COVER-LH	Necessary	689.00 FS	*551.20 FS
15	1		*REAR ALUMINIUM RIM-LH	Not Necessary	1,821.00 FS	*- FS
16	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
17	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
18	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
19	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
20	1		*METAL FILLER POWER	Not Necessary	280.00 FS	*- FS
21	1		*SUNDRIES	Necessary	400.00 FS	*9.28 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$\$)</b>	<b>15,381.00      5,041.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	300.00	0.00
3	TO INSTALL SOLAR FILM FOR LHS SIDE 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS,DISLODGE FOOR LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
7	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	400.00	280.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER.TO RENEW LHS REAR DOOR.TO CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	6,400.00	1,500.00
9	TO RESPRAY REAR BUMPER,LHS REAR FENDER,LHS REAR DOOR,BOTH REAR WHEEL ARCH TRIMS,DOOR COVER,LHS SILL PANEL,ROOF CHANNEL,DRAIN CHANNELDOOR ENTRANCE AND REAR END PANELLING	New	7,100.00	2,300.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO RENEW LHS REAR RIM.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	240.00
<b>Gross Labour Cost (\$\$)</b>			<b>18,672.00</b>	<b>4,872.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >