



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FY 4412R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER	TO REPAIR SEE LABOUR	60.00	-
1	HEADLAMP	SCRATCHED	100.00	100.00
1	HEADLAMP BRACKET	TO REPAIR SEE LABOUR	50.00	-
2	FORK INNER TUBES	NOT NECESSARY	420.00	-
2	FORK OUTER TUBES	TO REPAIR SEE LABOUR	240.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	175.00	-
1	FRONT RIM	TO REPAIR SEE LABOUR	480.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	150.00	-
1	FRONT RIM SHAFT	CUT	79.00	65.00
1	HANDLE BAR	BENT	90.00	90.00
1	HANDLE BAR END	SCRATCHED	45.00	45.00
1	SET SIDE MIRROR	BROKEN	150.00	150.00
1	CLUTCH LEVER HOLDER	CRACKED	135.00	135.00
1	BRAKE MASTER PUMP	DAMAGED	155.00	155.00
1	SET FRONT SIGNALS	BROKEN	100.00	100.00
2	FRONT FOOTREST	N/S TORN	120.00	60.00
2	FRONT FOOTREST BRACKET	BENT / TWISTED	80.00	80.00
1	BRAKE PEDAL	BENT	55.00	55.00
1	FUEL TANK	TO REPAIR SEE LABOUR	585.00	-
2	REAR FOOTREST	NOT NECESSARY	150.00	-
2	REAR FOOTREST BRACKET	NOT NECESSARY	230.00	-
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	650.00	-
1	EXHAUST PROTECTOR	BENT	150.00	150.00
1	REAR SIGNALS N/S	BROKEN	120.00	75.00
	LESS 10% DISCOUNT		-456.90	-126.00
			4,112.10	1,134.00

Report Ref No. CS/TP21008152/Utf3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET NUMBER PLATE (SN)	BENT	38.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE BEARING (SN)	NOT NECESSARY	85.00	-
1	FUEL TANK LOGO (PHANTOM) (SN)	SCRATCHED	38.00	38.00
1	E.R.P. IU (SN)	NOT NECESSARY	180.00	-
1	REAR BOX (SN)	CUT	380.00	200.00
1	REAR BOX BRACKET (SN)	BENT	180.00	180.00
			987.00	428.00
	<b><u>LABOUR</u></b>			
	TO PROVIDE TOWING SERVICE (LOD).		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.		400.00	250.00
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FENDER, HEADLAMP BRACKET, FORK OUTER TUBES, FRONT RIM, FUEL TANK AND EXHAUST ASSY.		420.00	300.00
			950.00	585.00
<b>GRAND TOTAL</b>			<b>6,049.10</b>	<b>2,147.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,700.00</b>

Report Ref No. CS/TP21008152/Utf3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.