

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008158/T1TCN2**Date:** 26/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00092042002

Claimant Vehicle No : SMU824A **Insured Vehicle No :** YP7446X

Date of Loss: 30/07/2021 Nature of Claim: TP Claim No: SNM21D204282/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU824A**

Make & Model: HONDA FREED, 1.5 G (A) Engine No: LEB7219853

Reg. Date: 28/07/2020 (Man. Year: 2020) Chassis No: GB73117051

Colour: White Odometer: 65815 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,980.00	3,286.00	8,694.00	72.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,370.00	4,480.00	76.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,830.00	4,656.00	13,174.00	73.89
Approved Total (Overridden) (\$\$)		3,700.00		
(\$\$)	17,830.00	3,700.00	14,130.00	79.25
+ GST 7.00/7.00% (\$\$)	1,248.10	259.00	989.10	79.25
Nett Amount (\$\$)	19,078.10	3,959.00	15,119.10	79.25

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 04/08/2021 Inspected At: 56 LOYANG WAY,
#04-04 LOYANG ENTERPRISE BUILDING
REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2022)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU824A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	711.00 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	144.00 FL	*- FL
3	1		*HEADLAMP RH	Cracked	1,820.00 FL	*1,820.00 FL
4	1		*HEADLAMP BRACKET RH	Cracked	39.00 FL	*39.00 FL
5	1		*FRONT GRILLE ASSY (NPA)	Not Necessary	0.00 FL	*- FL
6	1		*FRONT GRILLE CENTER CHROME	Not Necessary	785.00 FL	*- FL
7	1		*FRONT GRILLE TOP GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
8	1		*FRONT GRILLE LOGO-HONDA (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*FRONT BUMPER	Deformed	841.00 FL	*841.00 FL
10	1		*FRONT BUMPER LOWER	Not Necessary	117.00 FL	*- FL
11	1		*FRONT BUMPER RETAINER RH	Necessary	25.00 FL	*25.00 FL
12	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	75.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	350.00 FL	*- FL
14	1		*FRONT BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*FRONT BUMPER UNDERCOVER	Not Necessary	110.00 FL	*- FL
16	1		*FRONT FENDER RH	Bent	507.00 FL	*507.00 FL
17	1		*FRONT FENDER QUARTER WINDOW MOULDING RH	Not Necessary	58.00 FL	*- FL
18	1		*FRONT FENDER EMBLEM RH	Necessary	63.00 FL	*63.00 FL
19	1		*FRONT FENDER COWLING RH	Torn	125.00 FL	*125.00 FL
20	1		*FRONT SUPPORT PANEL	Not Necessary	625.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
22	1		*FRONT DOOR RH	Repair	888.00 FL	*- FL
23	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	122.00 FL	*- FL
24	1		*FRONT ABSORBER RH	Not Necessary	466.00 FL	*- FL
25	1		*FRONT LOWER ARM RH	Not Necessary	352.00 FL	*- FL
26	1		*FRONT KNUCKLE RH	Not Necessary	325.00 FL	*- FL
27	1		*FRONT KNUCKLE BEARING RH	Not Necessary	135.00 FL	*- FL
28	1		*FRONT BEARING HUB RH	Not Necessary	202.00 FL	*- FL
29	1		*FRONT DRIVE SHAFT RH	Not Necessary	978.00 FL	*- FL
30	1		*FRONT TIE ROD RH	Not Necessary	95.00 FL	*- FL
31	1		*FRONT TIE ROD END RH	Not Necessary	90.00 FL	*- FL
32	1		*FRONT STABILIZER LINK RH	Not Necessary	77.00 FL	*- FL
33	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
34	1		*FRONT FENDER CLIPS	Not Necessary	100.00 FS	*- FS
35	1		*FRONT FENDER QUARTER WINDOW SEALANT	Not Necessary	80.00 FS	*- FS
36	1		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
37	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
38	1		*FRONT RIM RH	Cut	3,000.00 FS	*500.00 FS
39	1		*FRONT TYRE RH	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,005.00	3,970.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,025.00	684.00
Total Parts (\$)	11,980.00	3,286.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
3	TO RNR FRONT FENDER QUARTER WINDOW	New	250.00	0.00
4	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
5	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
6	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
7	TO RNR UNDERCARRIAGE	New	250.00	0.00
8	TO CHECK WHEEL BALANCING	New	250.00	30.00
9	TO CHECK WATER LEAK	New	150.00	0.00
10	TO RNR FRONT AIR CON CONDENSER AND TOP UP GAS	New	300.00	0.00
11	TO RNR FRONT RADIATOR	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO PERFORM RUST PROOFING	New	400.00	30.00
14	TO RNR FRONT DOOR MECHANISM (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			5,850.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >