

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008159/ETF3N2**Date:** 01/09/2021**REFERENCE**

Insured/Claimant:	WONG SANG PANG	Policy No:	2100448719-05	
Date of Loss:	02/08/2021	Nature of Claim:	OD	Claim No: 1650438212SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH1383C	Engine No:	4B12QR5032
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	JMYXTGF3WGZ002267
Reg. Date:	22/01/2016 (Man. Year: 2015)	Odometer:	69848 km
Colour:	Grey		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Roadstone 4 mm	Rear Left Side:	Roadstone 4 mm
Front Right Side:	Roadstone 4 mm	Rear Right Side:	Roadstone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,467.12	7,946.38	1,520.74	16.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,385.00	5,355.00	30.00	0.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,852.12	13,301.38	1,550.74	10.44
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,252.12	12,701.38	1,550.74	10.88
+ GST 7.00/7.00% (S\$)	997.65	889.10	108.55	10.88
Nett Amount (S\$)	15,249.77	13,590.48	1,659.29	10.88

INSPECTION

Date of Assignment:	03/08/2021	
Date Inspected:	03/08/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	12.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,LH	Broken	2,135.00 FL	*2,135.00 FL
2	1		*HEADLAMP ASSY,RH	Broken	2,135.00 FL	*2,135.00 FL
3	1		*BRACKET,FR BUMPER SIDE,LH	Not Necessary	18.00 FL	*- FL
4	1		*BRACKET,FR BUMPER SIDE,RH	Not Necessary	18.00 FL	*- FL
5	1		*EXTENSION,FR BUMPER	Cut	428.00 FL	*428.00 FL
6	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	50.00 FL	*- FL
7	1		*GRILLE ASSY,RADIATOR	Missing	572.00 FL	*572.00 FL
8	1		*COVER,FR BUMPER	Not Necessary	25.00 FL	*- FL
9	1		*BRACKET,RADIATOR GRILLE,RH	Not Necessary	17.00 FL	*- FL
10	1		*BRACKET,RADIATOR GRILLE,LH	Not Necessary	13.00 FL	*- FL
11	1		*BRACKET,RADIATOR GRILLE,RH	Not Necessary	17.00 FL	*- FL
12	1		*BRACKET,RADIATOR GRILLE,LH	Not Necessary	13.00 FL	*- FL
13	1		*BRACKET,RADIATOR GRILLE	Not Necessary	12.00 FL	*- FL
14	1		*BRACKET,RADIATOR GRILLE	Not Necessary	10.00 FL	*- FL
15	1		*FENDER,FR RH	Dented	622.00 FL	*622.00 FL
16	1		*PANEL,HEADLAMP SUPPORT,UPR	Dented	230.00 FL	*230.00 FL
17	1		*PNL,HEADLAMP SUPT,UPR RH	Bent	58.00 FL	*58.00 FL
18	1		*COVER,ENG ROOM UNDER,FR	Broken	349.00 FL	*349.00 FL
19	1		*GARNISH,FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
20	1		*GARNISH,FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
21	1		*REINFORCEMENT,FR BUMPER	Dented	505.00 FL	*505.00 FL
22	1		*REINF,FR BUMPER SIDE,RH	Bent	69.00 FL	*69.00 FL
23	1		*REINFORCEMENT,FR BUMPER	Bent	135.00 FL	*135.00 FL
24	1		*COVER,FR BUMPER	Cut	281.00 FL	*281.00 FL
25	1		*GRILLE ASSY,RADIATOR	Repeated	572.00 FL	*- FL
26	1		*COVER,FR BUMPER	Not Necessary	25.00 FL	*- FL
27	1		*WHEEL,SPARE TIRE DISC	Not Necessary	1,102.00 FL	*- FL
28	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
29	1		*GARNISH,FR BUMPER SIDE	Not Necessary	48.00 FL	*- FL
30	1		*REINFORCEMENT,FR BMPR SIDE	Not Necessary	22.00 FL	*- FL
31	1		*FACE, FR BUMPER	Broken	863.00 FL	*863.00 FL
32	1		Supplementary *REINF, FR BUMPER SIDE, LH	Bent	60.00 FL	*60.00 FL
33	1		Supplementary *MOULDING, FR WHEEL ARCH, LH	Necessary	199.00 FL	*199.00 FL
34	1		Supplementary *MOULDING, FR WHEEL ARCH, RH	Necessary	199.00 FL	*199.00 FL
35	1		Supplementary *LLC 4L	Necessary	26.00 FL	*26.00 FL
36	1		Supplementary *HOOD	Dented	980.00 FL	*980.00 FL
37	1		Supplementary *PANEL, HEADLAMP SUPPORT, RH	Bent	58.00 FL	*58.00 FL
38	10		Supplementary *CLIPS	Necessary	20.00 FL	*20.00 FL
39	10		Supplementary *CLIPS	Necessary	30.00 FL	*30.00 FL
40	2		Supplementary *GROMMET, FRONT BUMPER	Necessary	8.00 FL	*8.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,286.00	10,314.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,818.88	2,367.62
Total Parts (\$\$)	9,467.12	7,946.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER,SUPPORT & AFFECTED AREA.REPAIR ON FRT LH FENDER	New	1,800.00	1,800.00
2	PAINT WORK FRT BUMPER,FRT BOTH FENDER & FRT RH DOOR	New	1,400.00	1,400.00
3	REMOVE & INSTALL RADIATOR,CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	PERFORM RUST PREVENTION	New	40.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
8	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	30.00	0.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
11	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	320.00	320.00
12	RESPRAY ON BONNET, LHF FRONT DOOR Supplementary	New	700.00	700.00
13	RESPRAY ON FRONT HEADLAMP SUPPORT PANEL & REINFORCEMENT Supplementary	New	350.00	350.00
14	REPAIR FRONT CHASSIS PLATE Supplementary	New	225.00	225.00
Gross Labour Cost (\$\$)			5,385.00	5,355.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >