



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /WONG SANG PANG Reg No/Reg Date SJH1383C / 22/01/201 Date In/Mileage 03/08/2021/ 0 Chassis No JMYXTGF3WGZ002267 Engine No 4B12QR5032 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12 Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	03/08/2021/ 13:07	QUK	282 / Kevin Leong	13842			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPALCE FRT BUMPER, FRT RH FENDER, SUPPORT & AFFECTED AREA 4 X 450								
REPAIR ON FRT LH FENDER								1400.00
E PNT98000								120.00
PAINT WORK FRT BUMPER, FRT BOTH FENDER & FRT RH DOOR 4 X 350								
E PNT88000								80.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR (photo)								
M SUNDRY								40.00
TO TOP UP AIRCON GAS								
M SUNDRY								30.00
PERFORM RUST PREVENTION								
A 54900099								120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								30.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								120.00
TO TRANSFER FRT RH RIM INCLUDING BALANCING								
B WHEELALIGNMENT								50.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								320.00
TO SUPPLY FRT NUMBER PLATE WITH FRAME								
M SUNDRY								30.00
TO APPLY ZERTONA COATING ON AFFECTED AREA 80 X 4 (Prande Saker agreed)								
M SUNDRY								20
SUNDRIES								
M HEADLAMP ASSY, LH / BR					1.00	2135.00	23.00	1643.95
M HEADLAMP ASSY, RH / BR					1.00	2135.00	23.00	1643.95
M BRACKET, FR BUMPER SIDE, LH 1 X NN					1.00	18.00	23.00	13.86
M BRACKET, FR BUMPER SIDE, RH 1 X NN					1.00	18.00	23.00	13.86
M EXTENSION, FR BUMPER / CNT 1 X NN					1.00	428.00	23.00	329.56
M COVER, HEADLAMP SUPT PANEL					1.00	50.00	23.00	38.50
M GRILLE ASSY, RADIATOR / MIS					1.00	572.00	23.00	440.44
M COVER, FR BUMPER 1 X NN					1.00	25.00	23.00	19.25

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /WONG SANG PANG Reg No/Reg Date SJH1383C / 22/01/201 Date In/Mileage 03/08/2021/ 0 Chassis No JMYXTGF3WGZ002267 Engine No 4B12QR5032 Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12 Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	03/08/2021/ 13:07	QUK	282 / Kevin Leong	13842

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET,RADIATOR GRILLE,RH	1.00	17.00	23.00	13.09
M BRACKET,RADIATOR GRILLE,LH	1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE,RH	1.00	17.00	23.00	13.09
M BRACKET,RADIATOR GRILLE,LH	1.00	13.00	23.00	10.01
M BRACKET,RADIATOR GRILLE	1.00	12.00	23.00	9.24
M BRACKET,RADIATOR GRILLE	1.00	10.00	23.00	7.70
M FENDER,FR RH	1.00	622.00	23.00	478.94
M PANEL,HEADLAMP SUPPORT,UPR	1.00	230.00	23.00	177.10
M PNL,HEADLAMP SUPT,UPR RH	1.00	349.00	23.00	268.73
M COVER,ENG ROOM UNDER,FR	1.00	220.00	23.00	169.40
M GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE	1.00	48.00	23.00	36.96
M REINFORCEMENT,FR BUMPER	1.00	505.00	23.00	388.85
M REINFORCEMENT,FR BMRP SIDE	1.00	22.00	23.00	16.94
M REINF,FR BUMPER SIDE,RH	1.00	69.00	23.00	53.13
M REINFORCEMENT,FR BUMPER	1.00	135.00	23.00	103.95
M COVER,FR BUMPER	1.00	281.00	23.00	216.37
M GRILLE ASSY,RADIATOR	1.00	572.00	23.00	440.44
M COVER,FR BUMPER	1.00	25.00	23.00	19.25
M WHEEL,SPARE TIRE DISC	1.00	1102.00	23.00	848.54

Steve (LKK)
3/8/21, 3:00pm00-MAL
EXCII-?
P/PM B-L M
12 djsLKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

Confirm & accepted by survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Nett	11,651.35
7% GST on	815.59
Total Payable	12,466.94

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.