



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 02.08.2021
Emailed : 30.08.2021, 3.50pm
Date Survey : 03.08.2021

VEHICLE NO : SJH 1383 C
MODEL : MIT OUTLANDER 2.4
WIP : 13842

Material	:	\$	<u>7,926.38</u>
Labour	:	\$	<u>5,375.00</u>
Sub-Total	:	\$	<u>13,301.38</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>12,701.38</u>
GST 7%	:	\$	<u>889.10</u>
Grand Total	:	\$	<u>13,590.48</u>
Finalise By/Date	:	<u>LOI / 30/08/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 03/08/2021	Cust No/Name	/WONG SANG PANG
	Reg No/Reg Date	SJH1383C / 22/01/2016
	Date In/Mileage	03/08/2021/ 69847
	Chassis/Package	JMYXTGF3WGZ002267 /FS515N
	Engine No	4B12QR5032
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	30/08/2021/ 11:17	BLK	260 / AiTing	13842		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							✓ 1800.00
REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, FRONT SUPPORT PANEL, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							
E PNT98000							✓ 1400.00
RESPRAY ON FRONT BUMPER, BOTH FRONT FENDER, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME							
E PNT88000							✓ 120.00
REMOVE & INSTALL RADIATOR, & A/COND CONDENSER TO FACILITATE REPAIR							
M SUNDRY							✓ 40.00
PERFORM RUST PREVENTION ON AFFECTED AREAS							
A 54900099							✓ 30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							✓ 120.00
CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE							
B WHEELALIGNMENT							✓ 120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							✓ 320.00
APPLY ZERTONA COATING ON AFFECTED AREAS							
M SUNDRY							✓ 20.00
SUNDRIES							
E PNT98000							700.00
RESPRAY ON BONNET, LHF FRONT DOOR → Supp.							
S SPECIALISTJOB							✓ 50.00
SUPPLY & REPLACE FRONT NUMBER PLATE WITH FRAME							
A 55900099							✓ 80.00
VACUUM & TOP UP A/COND GAS							
E PNT88000							225.00
REPAIR FRONT CHASSIS PLATE → Supp.							
E PNT98000							350.00
RESPRAY ON FRONT HEADLAMP SUPPORT PANEL & REINFORCEMENT → Supp.							
X EXC							-600.00
INSURANCE EXCESS							



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 03/08/2021	Cust No/Name	/WONG SANG PANG
	Reg No/Reg Date	SJH1383C / 22/01/2016
	Date In/Mileage	03/08/2021/ 69847
	Chassis/Package	JMYXTGF3WGZ002267 /FS515N
	Engine No	4B12QR5032
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	30/08/2021/ 11:17	BLK	260 / AiTing	13842	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
X	HEADLAMP ASSY,LH		1.00	✓ 2135.00	23.00	1643.95
X	EXTENSION,FR BUMPER		1.00	✓ 428.00	23.00	329.56
X	GRILLE ASSY,RADIATOR		1.00	✓ 572.00	23.00	440.44
X	FENDER,FR RH		1.00	✓ 622.00	23.00	478.94
X	PANEL,HEADLAMP SUPPORT,UPR		1.00	✓ 230.00	23.00	177.10
X	PNL,HEADLAMP SUPT,UPR RH		1.00	✓ 58.00	23.00	44.66
X	COVER,ENG ROOM UNDER,FR		1.00	✓ 349.00	23.00	268.73
X	GARNISH,FR BUMPER SIDE		1.00	✓ 220.00	23.00	169.40
X	GARNISH,FR BUMPER SIDE		1.00	✓ 112.00	23.00	86.24
X	REINFORCEMENT,FR BUMPER		1.00	✓ 505.00	23.00	388.85
X	REINF,FR BUMPER SIDE,RH		1.00	✓ 69.00	23.00	53.13
X	REINFORCEMENT,FR BUMPER		1.00	✓ 135.00	23.00	103.95
X	COVER,FR BUMPER		1.00	✓ 281.00	23.00	216.37
X	FACE,FR BUMPER		1.00	863.00	23.00	664.51
X	REINF,FR BUMPER SIDE,LH		1.00	60.00	23.00	46.20
X	MOULDING,FR WHEEL ARCH,LH		1.00	199.00	23.00	153.23
X	MOULDING,FR WHEEL ARCH,RH		1.00	199.00	23.00	153.23
X	PANEL,HEADLAMP SUPPORT,RH		1.00	58.00	23.00	44.66
X	CLIP,ENG ROOM COVER		10.00	2.00	23.00	15.40
X	CLIP,RR BUMPER		10.00	3.00	23.00	23.10
X	GROMMET,FR BUMPER		2.00	4.00	23.00	6.16
X	LLC 4L		1.00	26.00	23.00	20.02
X	HOOD		1.00	980.00	23.00	754.60
X	HEADLAMP ASSY,RH		1.00	✓ 2135.00	23.00	1643.95
Z TEXT						
AIG OD CLAIM						
DOA : 02.08.21						
SURVEYOR STEVE-LKK 03.08.21						
POLICY NO : 2100448719-05 REPAIR 10D+2D=12D						
Guarantee Your Warranty, Maintain with Cycle & Carriage!						

Parts	7,926.38	Nett	12,701.38
Labour	4,945.00	7% GST on	12701.38
Standard Menu	0.00		889.10
Specialist Job	50.00	Total Payable	13,590.48
Diagnostics Job	0.00		
Sundry/Others	-220.00		
Total(w/o GST)	12,701.38		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SJH 1383 C

<u>Materials</u>		<u>Cost (\$)</u>
1	Face, Fr bumper	863.00 — BR
2	Reinf, Fr bumper side, LH	60.00 — BT
3	Moulding, Fr wheel arch, LH	199.00 — nec
4	Moulding, Fr wheel arch, RH	199.00 — nec
5	Panel, Healdmap support, RH	58.00 — BT
6	clips (x10)	20.00 — nec
7	clips (x10)	30.00 — nec
8	Grommet, front bumper (x2)	8.00 — nec
9	LLC 4L	26.00 — nec
10	Hood	980.00 — DD

Total	2,443.00
Less 23%	561.89
Total Materials	1,881.11

<u>Labour</u>		<u>Cost (\$)</u>
1	Respray on bonnet, LHF front door	700.00 —
2	Repair front chassis plate	225.00 —
3	Respray on front headlamp support panel, & reinforcement	350.00 —
Total Labour		1,275.00
Taxable Amount		3,156.11
7% GST		220.93
Grand total		<u><u>3,377.04</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SJH 1383C

WIP: 13842

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Painting on Bonnet	? / SUPP		—	
2	Painting on Frt LH Door	? / SUPP		—	
3	Face Front Bumper	? / SUPP		— RR	
4	Reinforcement Front Bumper UPR	? / SUPP	(Metal)	— BT	
5	Reinforcement Front Bumper Side LH	? / SUPP	(1")	— BT	
6	Reinforcement Front Bumper Side RH	? / SUPP	(1")	— BT	
7	Reinforcement Front Bumper LWR	? / SUPP		— DD	
8	Moulding Front Wheel Arch LH	? / SUPP		— MC	
9	Moulding Front Wheel Arch RH	? / SUPP		— MC	
10	Panel Headlamp Support UPR RH	? / SUPP	(UPPR)	— DD	Steve
11	Panel Headlamp Support Side RH	? / SUPP	(Vertical)	— DD	6/8/21
12	Clip Front Bumper & Under Cover	? / SUPP		— MC	
13	Clip Support Cover	? / SUPP		— MC	
14	Grommet Headlamp	? / SUPP		— MC	
15	Couplant 4L	? / SUPP		— MC	
16	Washer Nozzle Here	? / SUPP			
17	Bonnet Assy	? / SUPP		— DD	
18	Repair Front Bonnet Chassis Plate	? / SUPP		\$ 225	
19	Renew Headlamp Support & Reinforcement	? / SUPP			
20	Respray Headlamp Support & Reinforcement	? / SUPP		\$ 345.50	
	Renew Front Bonnet				

DATE	TAKEN BY

Add 62 day - Total : 12 day

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBOARD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL:

Outlander

SURVEYOR:

Steve - Luch

Work Order: R001509
License: SJH1383C
Technician: ALVIN (108)
Mileage: 69847
Date: 18.8.21 11:44

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : All Wheel Drive

Front : Left

Actual	Before	Specified Range
0°14'	0°06'	-0°10' 0°50'
2°27'	2°39'	2°05' 3°05'
0°03'	0°05'	-0°02' 0°06'
13°45'	13°36'	11°15' 14°15'
13°59'	13°42'	11°05' 15°05'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°08'	0°16'	-0°10' 0°50'
3°14'*	3°15'*	2°05' 3°05'
0°03'	0°01'	-0°02' 0°06'
13°52'	13°54'	11°15' 14°15'
14°00'	14°10'	11°05' 15°05'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°06'	-0°09'	-0°30' 0°30'
-0°47'*	-0°36'*	-0°30' 0°30'
-0°06'	-0°18'	
0°06'	0°07'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°39'	-0°47'	-1°15' 0°15'
0°07'	0°03'	0°02' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°58'	-0°47'	-1°15' 0°15'
0°06'	0°17'*	0°02' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°19'	0°00'	-0°30' 0°30'
0°13'	0°20'	0°04' 0°24'
0°01'	-0°07'	

SSH1383C

After erase all DTC

All DTCs

2021.08.18

Setting	
Item	Information
M.U.T.-3 Version	SEW21031-00
V.C.I. Version	B179
Vehicle Information	GF3W 2016MY

All DTCs

2021.08.18

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs			
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs			
	AUTO CRUISE	GAS_0E640000		Non-target System			
	4WS/Electric Power Steering	EPS_45880040		No DTCs			
	ABS/ASC/ASTC/WSS (A.S.C.)	ABS_40080015		No DTCs			
	SRS-AIR BAG	ORC_81047302		No DTCs			
	Air Conditioner	AC_80080011		No DTCs			
	ETACS	ETACS_83040801		No DTCs			
	Meter	MTR_84084001		No DTCs			
	Steering Angle Sensor	GS_SAS_47000100		Non-target System			
	AWC	AWC_16080002		No DTCs			
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error			
	LIN	ETACS_83040801		Non-target System			
	Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active		
	KOS/IMMO/Keyless (IMMOBI & KOS)	KOS_8A880020		No DTCs			

All DTCs

2021.08.18

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
	OSS	OSS_958000B		No DTCs			
	CORNER SENSOR/BACK SENSOR	CornetSens_96000001		Non-equipped System or Communication Error			