



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AVIVA LTD C/O :TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWER SINGAPORE 068807		Ref: CS/AVI21008160/Uuf3e2 Date: 07/10/2021 Code: AVI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SMR 570Y	Veh. Inspected	SGP 3525R
Policy No.	CF.SKS.so.0555.21-aviva	Coverage (\$)	0.00
Claim No.	G0067439/SMR570Y/JH	Excess (\$)	0.00
Assign From	STELLA OW	Assign Date	03/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ACR507033925	Colour	BLACK
Odometer	274218 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	22/02/2020	Inspection Date	12/08/2021
Survey held at	50 East Coast Road 4th floor Car Park Singapore 42		
Repairer	LUSH AUTOMOTIVE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	