

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21008161/UGA3Q2  
**Date:** 12/10/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900078008   |
| <b>Claimant Vehicle No :</b> | SKX9292H                             | <b>Insured Vehicle No :</b> | SMK1656P     |
| Date of Loss:                | 31/07/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4297577166SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKX9292H</b>                   |             |                   |
| Make & Model:               | MAZDA 3, 1.5 SEDAN L SP.6EAT (A)  | Engine No:  | P520337087        |
| Reg. Date:                  | 31/12/2015 (Man. Year: 2015)      | Chassis No: | JM6BM42A8G0328349 |
| Colour:                     | White                             | Odometer:   | 84936 km          |
| Engine Capacity:            | 1496 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 205/60 R16 | Rear Tyre Size:  | 205/60 R16 |
| Front Left Side:  | Nexen 6 mm | Rear Left Side:  | Nexen 6 mm |
| Front Right Side: | Nexen 6 mm | Rear Right Side: | Nexen 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 3,889.44          | 2,565.84          | 1,323.60          | 34.03         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,280.00          | 820.00            | 1,460.00          | 64.04         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>6,169.44</b>   | <b>3,385.84</b>   | <b>2,783.60</b>   | <b>45.12</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,700.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                        | <b>6,169.44</b> | <b>2,700.00</b> | <b>3,469.44</b> | <b>56.24</b> |
| <b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b> |                 | 400.00          |                 |              |
| <b>(S\$)</b>                                    |                 | 3,100.00        |                 |              |
| <b>Liabale Amount (50.00%) (S\$)</b>            |                 | <b>1,550.00</b> |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 36.45           |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>1,586.45</b> |                 |              |

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 03/08/2021 Inspected At:

Eco Automobile Claims & Repair Pte Ltd - Bartley Biz Center (HQ)  
 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTER  
 Singapore 417808

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's | Amount     |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER                       | Distorted     | 955.50 FL  | *955.50 FL |
| 2   | 2   |          | *FRONT BUMPER SIDE RETAINER LH & RH | Not Necessary | 174.20 FL  | *- FL      |
| 3   | 1   |          | *FRONT BUMPER SIGNAL LAMP RH        | Cracked       | 255.10 FL  | *255.10 FL |
| 4   | 1   |          | *FRONT BUMPER SIGNAL LAMP COVER RH  | Scratched     | 65.30 FL   | *65.30 FL  |
| 5   | 1   |          | *FRONT BUMPER LOWER GRILLE          | Not Necessary | 124.20 FL  | *- FL      |
| 6   | 1   |          | *FRONT BUMPER UPPER GARNISH         | Warped        | 310.50 FL  | *178.00 FL |
| 7   | 1   |          | *FRONT BUMPER REINFORCEMENT         | Dented        | 459.20 FL  | *459.20 FL |
| 8   | 1   |          | *FORNT GRILLE                       | Cracked       | 220.40 FL  | *220.40 FL |
| 9   | 1   |          | *FORNT GRILLE LOGO                  | Not Necessary | 71.00 FL   | *- FL      |
| 10  | 1   |          | *FORNT GRILLE CHROME LH & RH        | O/S Cracked   | 353.40 FL  | *176.70 FL |
| 11  | 1   |          | *FORNT GRILLE BRACKET LH & RH       | O/S Cracked   | 70.20 FL   | *35.10 FL  |
| 12  | 2   |          | *FORNT GRILLE BRACKET PIN           | Not Necessary | 37.80 FL   | *- FL      |
| 13  | 2   |          | *FORNT GRILLE BRACKET PIN GROMMET   | Not Necessary | 38.20 FL   | *- FL      |
| 14  | 1   |          | *FRONT GRILLE UPPER GARNISH         | Repeated      | 351.40 FL  | *- FL      |
| 15  | 1   |          | *FRONT HEADLAMP RHS                 | Cracked       | 890.00 FL  | *812.00 FL |
| 16  | 1   |          | *FRONT HEADLAMP PANEL RHS           | Repair        | 355.00 FL  | *- FL      |
| 17  | 1   |          | *FRONT HEADLAMP BRACKET RH          | Not Necessary | 55.40 FL   | *- FL      |
| 18  | 1   |          | *FRONT BUMPER CLIPS                 | Necessary     | 60.00 FS   | *40.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>4,846.80</b> | <b>3,197.30</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 957.36          | 631.46          |
| <b>Total Parts (\$\$)</b>                                  | <b>3,889.44</b> | <b>2,565.84</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                       | Lab.Type | Repairer's      | Amount        |
|--------------------------------|---------------------------------------------------------------------------------------------------|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>     |                                                                                                   |          |                 |               |
| 1                              | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS | New      | 1,000.00        | 300.00        |
| 2                              | TO SUPPLY PAINT MATERIALS EXPANDABLE ITEM & PUTTY,RESPRAY PAINT ON PARTS REPLACED                 | New      | 800.00          | 500.00        |
| 3                              | TO REMOVE/REFIX AND CHECK WIRING OF ALL ELECTRICAL COMPONENT}                                     | New      | 150.00          | 20.00         |
| 4                              | TO REMOVE AND REFIX WIRING AT DAMAGED AREAS AND FOCUS HEADLAMP BEAM }                             | New      | 120.00          | 0.00          |
| 5                              | TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS                                                  | New      | 210.00          | 0.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                   |          | <b>2,280.00</b> | <b>820.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >