

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref		CS3/SGK21008162/Vvf3e2	
	30 CECIL STREET	NGAPORE PTE LTD , LEVEL 12 VER SINGAPORE 049712	Dat	e:	10/08/2021	
			Cod	de:	AIG	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected		FBR 9899X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	6005788	Excess (\$)		0.00	
	Assign From	KENNETH NEO	Assign Date		03/08/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CB400XA	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JH2NC5696KK000342	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/80 R19	DUNLOP		7 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	190/60 R17	DUNLOP		7 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/S	BODY.	(		
5.	General Information					
	Accident Date	28/07/2021	Inspect Date / Time	9	03/08/2021 ( 02:30 PM )	
	Survey held at	urvey held at 10 Kaki Bukit Road 2 #01-06				
	Repairer	Repairer BIKE IMAGE MOTOR TRADING				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SGK21008162/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser