

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008163/UVCE2

Date: 29/09/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00002632101

Claimant Vehicle No : SLN5480Z

Insured Vehicle No : SMU4344S

Date of Loss: 31/07/2021

Nature of Claim: TP

Claim No: SNM21D204276/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN5480Z**

Make & Model: HONDA JAZZ, 1.3 (A)

Engine No: L15B31191267

Reg. Date: 08/05/2017 (Man. Year: 2016)

Chassis No: JHMGK5850HX201776

Colour: Beige

Odometer: 59661 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size:

185/55 R16

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,740.88	1,888.78	1,852.10	49.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,070.00	7,550.00	7,520.00	49.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,810.88	9,438.78	9,372.10	49.82
+ GST 7.00/7.00% (S\$)	1,316.76	660.71	656.05	49.82
Nett Amount (S\$)	20,127.64	10,099.49	10,028.15	49.82

INSPECTION

Date of Assignment: 03/08/2021

Date Inspected: 04/08/2021

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2021)
Parts:	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN5480Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RUBBER C WINDSHIELD DAMPER	Necessary	9.15 FS	*9.15 FS
2	2		*RUBBER WINDSHIELD DAMPER	Necessary	11.10 FS	*11.10 FS
3	1		*DAMPER STD 5X5	Necessary	6.82 FS	*6.82 FS
4	1		*WINDSCREEN SEALANT (N)	Necessary	60.00 FS	*60.00 FS
5	1		*TAILGATE COMP	Badly Dented	584.40 FS	*584.40 FS
6	1		*LINING ASSY TAILGATE LOWER	Not Necessary	45.97 FS	*- FS
7	1		*POCKET TAILGATE LINING PULL	Not Necessary	4.42 FS	*- FS
8	1		*LINING ASSY, RR. PANEL	Twisted	45.60 FS	*45.60 FS
9	1		*LID ASSY SPARE TIRE	Not Necessary	151.72 FS	*- FS
10	1		*BOX ASSY CARGO FLOOR	Torn	91.57 FS	*91.57 FS
11	1		*WEATHER STRIP TAILGATE	Torn	69.22 FS	*69.22 FS
12	1		*LOCK ASSY, TAILGATE	Bent / Twisted	67.57 FS	*67.57 FS
13	1		*PANEL COMP RR.	Badly Dented	256.20 FS	*256.20 FS
14	1		*GUTTER COMP, L. RR. PILLAR LOWER	Repair	70.95 FS	*- FS
15	1		*PANEL SET, RR. FLOOR	Repair	546.52 FS	*- FS
16	1		*STIFFENER COMP, L. RR. SIDE	Repair	69.52 FS	*- FS
17	1		*FACER RR. BUMPER	Dented	401.92 FS	*401.92 FS
18	1		*SPACER RR. BUMPER	Bent	8.62 FS	*8.62 FS
19	1		*SPACER L. RR. BUMPER	Bent	8.62 FS	*8.62 FS
20	1		*GARNISH L. RR. BUMPER	Not Necessary	11.40 FS	*- FS
21	1		*CLIP, BUMPER (5PCS)	Necessary	8.62 FS	*8.62 FS
22	1		*OIL SHEET	Not Necessary	32.55 FS	*- FS
23	4		*ACT RR. SENSOR	Serviceable	320.00 FS	*- FS
24	1		*NUMBER PLATE WITH CASING-L(N)	Serviceable	45.00 FS	*- FS
25	1		*LIGHT ASSY RR. LID	Not Necessary	69.90 FS	*- FS
26	1		*LIGHT ASSY L. LID	Not Necessary	69.90 FS	*- FS
27	1		*TAILLIGHT ASSY, R.	Not Necessary	191.70 FS	*- FS
28	1		*TAILLIGHT ASSY L.	Cracked	191.70 FS	*191.70 FS
29	1		*BUZZER ASSY SMART	Cracked	48.37 FS	*48.37 FS
30	1		*ANTENNA ASSY L.F.	Not Necessary	47.40 FS	*- FS
31	1		*SUNDRIES	Necessary	50.00 FS	*10.00 FS
32	1		*EMBLEM RR.	Necessary	9.30 FS	*9.30 FS
33	1		*LINING ASSY L. TRUNK	Not Necessary	135.15 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,740.88** **1,888.78**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	120.00
2	REMOVE & INSTALL REVERSE SENSORS - 4 PCS (N)	New	200.00	150.00
3	BODY JOINT SEALANT	New	200.00	100.00
4	BODY UNDERSIDE COATING (N)	New	150.00	100.00
5	APPLY BODY UNDERSIDE COATING (N)	New	450.00	250.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	520.00	350.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
8	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
9	REMOVE & RENEW RR FLOOR INSULATOR (N)	New	450.00	0.00
10	REMOVE & INSTALL EXHAUST SYSTEM (N)	New	450.00	0.00
11	REMOVE & INSTALL FUEL TANK FUEL PIPES (N)	New	450.00	0.00
12	REMOVE & INSTALL RR SEATS LININGS GARNISHES	New	520.00	0.00
13	REMOVE & INSTALL RR.WINDSCREEN (N)	New	650.00	650.00
14	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	650.00	450.00
15	CUT & RENEW RR FLOOR PANEL. STRAIGHTEN FENDERS ALIG	New	5,500.00	2,600.00
16	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	New	3,800.00	2,080.00
Gross Labour Cost (\$\$)			15,070.00	7,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >