

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008167/ABS3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027046
Claimant Vehicle No :	SDJ8810B	Insured Vehicle No :	SMY7954R
Date of Loss:	01/08/2021	Nature of Claim:	TP
		Claim No:	2902533506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ8810B		
Make & Model:	MERCEDES-BENZ E220, 2.0 (A)	Engine No:	65492080031391
Reg. Date:	12/10/2016 (Man. Year: 2016)	Chassis No:	WDD2130042A057800
Colour:	Silver	Odometer:	48847 km
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/35 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,664.00	7,275.20	5,388.80	42.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,850.00	1,500.00	44.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,014.00	9,125.20	6,888.80	43.02
Approved Total (Overridden) (S\$)		7,300.00		

Nett Amount (S\$)	16,014.00	7,300.00	8,714.00	54.41
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,147.45		

INSPECTION

Date of Assignment: 02/08/2021

Date Inspected: 02/08/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Ysk Auto Workshop (HQ)
No.1 Kaki Bukit Avenue 6, #01-49 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,825.00 F	*1,825.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
3	1		*REAR BUMPER SIDE HOLDER	O/S Damaged	188.00 F	*94.00 FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	58.00 F	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Deformed	685.00 F	*685.00 FL
6	1		*REAR BUMPER LOWER CHROME MOULDING	Cut	388.00 F	*388.00 FL
7	2		*REAR BUMPER EXHAUST CHROME MOULDING	Not Necessary	336.00 F	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	769.00 F	*769.00 FL
9	1		*REAR BUMPER INNER FRAME	Cracked	278.00 F	*278.00 FL
10	2		*REAR BUMPER EXHAUST CHROME MOULDING BRACKET	Cracked	190.00 F	*190.00 FL
11	1		*REAR BUMPER LOWER COVER	Not Necessary	245.00 F	*- FL
12	1		*REAR BUMPER KICK SENSOR	Not Necessary	322.00 F	*- FL
13	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,060.00 F	*530.00 FL
14	1		*REAR END PANEL	Repair	1,350.00 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	156.00 F	*- FL
16	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
17	1		*BOOTLID	Buckled	2,293.00 F	*2,293.00 FL
18	1		*BOOTLID LOCK	Not Necessary	283.00 F	*- FL
19	1		*BOOTLID WEATHERSTRIPE	Not Necessary	261.00 F	*- FL
20	1		*MERCEDES LOGO	Necessary	85.00 F	*85.00 FL
21	1		*TAILLAMP	O/S Cracked	1,550.00 F	*775.00 FL
22	1		*TAILLAMP LOWER BRACKET	O/S Cracked	232.00 F	*116.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,664.00	8,078.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	802.80
Total Parts (\$)	12,664.00	7,275.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAY PAINTING	New	1,200.00	750.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	150.00	60.00
5	TO PERFORM DIAGNOSTIC	New	200.00	120.00
6	TO SPRAY TUFF COAT	New	150.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO REMOVE REAR CAMERA	New	100.00	0.00
9	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			3,350.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >