9/15/21, 10:02 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI21008171/R1VCN2

**Date:** 15/09/2021

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MW009206

Claimant Vehicle CLOSOGO POLICE CONTROL OF CO

No: SHC308C Insured Vehicle No: SKW1503H

Date of Loss: 29/07/2021 Nature of Claim: TP Claim No: M2103508

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC308C

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2G12237

Reg. Date: 08/01/2020 (Man. Year: 2019) Chassis No: JTDKB3FU103090434

Colour: Yellow Odometer: 0 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	926.12	414.45	511.67	55.25
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	600.00	220.00	26.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,757.12	1,025.45	731.67	41.64
+ GST 7.00/7.00% (S\$)	123.00	71.78	51.22	41.64
Nett Amount (S\$)	1,880.12	1,097.23	782.89	41.64

**INSPECTION** 

Date of Assignment: 04/08/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 02/08/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2021)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC308C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
1		*REAR BUMPER CENTER MOULDING	Scratched	451.25 FL	-	*414.45 FS
10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	-	*- FL
1		*REVERSE SENSORS	Not Necessary	180.00 F	-	*- FS
nchise	part. S=SpcN	Nett. L=ListItemDisc.	-			
			Sub Total (S\$)	1,112.65	414.45	
		- List Item Discount on L Item	ns 20.00/20.00% (S\$)	186.53	0.00	
			Total Parts (S\$)	926.12		414.45
	1 1 10 1	1 1 10 1	1 *REAR BUMPER CENTER MOULDING 10 *REAR BUMPER CLIPS 1 *REVERSE SENSORS achise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER Repair 1 *REAR BUMPER CENTER MOULDING Scratched 10 *REAR BUMPER CLIPS Not Necessary 1 *REVERSE SENSORS Not Necessary 1 chise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	1       *REAR BUMPER       Repair       459.40 FL         1       *REAR BUMPER CENTER MOULDING       Scratched       451.25 FL         10       *REAR BUMPER CLIPS       Not Necessary       22.00 FL         1       *REVERSE SENSORS       Not Necessary       180.00 F         Inchise part. S=SpcNett. L=ListItemDisc.       Sub Total (S\$)       1,112.65         - List Item Discount on L Items 20.00/20.00% (S\$)       186.53	1       *REAR BUMPER       Repair       459.40 FL       -         1       *REAR BUMPER CENTER MOULDING       Scratched       451.25 FL       -         10       *REAR BUMPER CLIPS       Not Necessary       22.00 FL       -         1       *REVERSE SENSORS       Not Necessary       180.00 F       -         1       *Reverse Sensors       Not Necessary       180.00 F       -         1       *Sub Total (S\$)       1,112.65       414.45         - List Item Discount on L Items 20.00/20.00% (S\$)       186.53       0.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount			
Misc	Miscellaneous Items							
1	1	OD/TP Case (Insurer)		11.00	11.00			
			Sub Total (S\$)	11.00	11.00			

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	0.00
		Gross Labour Cost (S\$)	820.00	600.00
	Reg	port was unsubmitted during this print-out.		

< END OF ESTIMATES >