(08/21/13) wef ASS. REC. BY: Cassus	821A				
ASSIGNMENT					
From: Date: Estimated Cost:	Veh No: SHC 3782X Yr Regn: 2019 / WOV  Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax? / Prime Mover /				
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or				
To Inspect Vehicle No:	lake: Hymnogy lowing Her FLI-60cf c.c (580				
at Workshop m/s	Colour Bus A/C: Insured / Std / NI / NA				
of	Sp.Reading 265150 T/Radio: Insured / Std / NI / NA				
Insured: NTLC	Eng/No:				
Policy No.	C/No: KMHC851CVLU188159.				
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt				
Sum Insured: Excess:	Steering: Iporder / Jammed / Leaked / Burnt or				
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or				
Make of Veh:	Modi : NTT / S/Rim / STD A/Rim or				
	Tyre Size: F: 195 65R15				
(Policy Condition)	R: -i				
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /				
repair at the time of inspection.	TOYO/YOKO or WESTLAKE				
Bal. or Market Value:	Front Rear				
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm				
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm				
Est. Repairs: days Res.: Yes or No	D.O.A. 30 07 21 D.O.I. 02/08/21				
Lum Sum: % 3 Val.: Yes or No	Survey held at Compost Light				
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or				
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision.					
Date / Time Action / Instruction					
· · · · · · · · · · · · · · · · · · ·					
4					
Date/Time, File Pass to? Days Of Repair:					
1) Final Paner					
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:				
2) Add Fee	: : Site Insp (\$ )S+RSsi				
	: Interview (\$ ) Photos				
Report Format :	: Tech. Invs (\$ ) Others				
Lump Sum / I.B.I: (\$	:Weekend (\$				
	TOTAL				

Sus I Van I Van

: HYUNDAI IONIQ G3

CHIANG/CHINA

Qty	Parts Description/ Labour	Туре	Unit Price	Amount	
	FRONT DOOR OUTER HANDLE BH			\$234.80	
	FRONT DOOR PROTECTOR RH 902 /			\$110.10	
	REAR DOOR PROTECTOR RH 500			\$125.30	
1	REAR WHEEL COVR RH 500			\$346.40	
	SUB TOTAL	1		\$816.60	
	LESS 20%			\$163.32	
	DISCOUNTED TOTAL			\$653.28	
1	FRONT DOOR COMFORT LOGO STICKER	NN		\$75.00	
:	REAR DOOR COMFORT APP STICKER			\$80.00	
				\$155.00	
	Labour Charge Panel Beating Spray Painting Charge Remove/refix upholstery Check Wiring TOTAL LABOUR ESTIMATE TOTAL		35 50	\$600.00 \$900.00 \$90.00 \$60.00 \$1,650.00 \$2,458.28	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify

- the Repairer of the following: · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
3 days
43
02/08/21@1550
Ras after rapair