



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 732K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	COVER-FR BUMPER	DEFORMED	430.90	430.90
1	PANEL-FENDER RH	BENT	588.80	588.80
1	LAMP ASSY-HEAD RH	TO REPAIR SEE LABOUR	1,993.65	-
1	BRACKET-FR BUMPER SIDE SU	SERVICEABLE	35.00	-
	LESS 20% DISCOUNT		-609.67	-203.94
			2,438.68	815.76
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ADVERTISEMENT STICKER-FENDER (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF LAMP ASSY-HEAD RH.		800.00	700.00
	SPRAYPAINT CHARGE.		600.00	500.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	CHECK ALL LIGHTING.	NOT NECESSARY	50.00	-
			1,500.00	1,230.00
	<b>GRAND TOTAL</b>		<b>4,038.68</b>	<b>2,145.76</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,700.00</b>

Report Ref No. NS/INC21008173/R1tcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.