

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008176/AEA3Q2**Date:** 21/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJK4117U **Insured Vehicle No :** SMV9639D
 Date of Loss: 29/07/2021 Nature of Claim: TP Claim No: MFL2021D0003259

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK4117U**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4780749
 Reg. Date: 20/10/2008 (Man. Year: 2008) Chassis No: MR053ZEE106113401
 Colour: White Odometer: 345918 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm
 Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,009.27	3,641.67	3,367.60	48.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	1,980.00	2,260.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,249.27	5,621.67	5,627.60	50.03
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	11,249.27	4,500.00	6,749.27	60.00
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,987.45		

INSPECTION

Date of Assignment: 03/08/2021
 Date Inspected: 03/08/2021 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
 Singapore 417807
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK4117U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	839.40 FL	*839.40 FL
2	1		*REAR BOOTLID LOGO	Necessary	87.60 FL	*87.60 FL
3	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	81.00 FL	*81.00 FL
4	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	68.00 FL	*68.00 FL
5	1		*REAR BOOTLID LOCK SWITCH	Not Necessary	195.00 FL	*- FL
6	1		*REAR BOOTLID INNER LOCK	Damaged	284.50 FL	*284.50 FL
7	1		*REAR BOOTLID INNER TRIM	Not Necessary	265.40 FL	*- FL
8	1		*REAR BOOTLID W/STRIP	Cut	232.80 FL	*232.80 FL
9	2		*REAR BOOTLID LAMP LH & RH	Not Necessary	721.80 FL	*- FL
10	2		*REAR NUMBER PLATE LAMP LH & RH	Not Necessary	211.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	676.70 FL	*576.00 FL
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	443.70 FL	*- FL
13	2		*REAR BUMPER SIDE BRACKET LH & RH	Dented	137.00 FL	*137.00 FL
14	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	238.40 FL	*90.00 FL
15	2		*REAR BUMPER REFLECTOR LH & RH	Not Necessary	275.60 FL	*- FL
16	1		*REAR BUMPER SPONGE	Cracked	169.00 FL	*169.00 FL
17	1		*REAR END PANEL	Dented	615.30 FL	*615.30 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	278.50 FL	*278.50 FL
19	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	475.80 FL	*- FL
20	1		*REAR SPARE TYRE PANEL	Not Necessary	797.00 FL	*- FL
21	1		*REAR SMART KEYLESS ANTENNA	Not Necessary	195.20 FL	*- FL
22	1		*REAR TAILLAMP LH	Cut	428.60 FL	*365.00 FL
23	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
24	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
25	1		*SET REAR BOOTLID LAMP CLIPS	Not Necessary	100.00 FS	*- FS
26	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
27	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*TAILLAMP RH	Cut	428.60 FL	*365.00 FL
29	2		*REAR BUMPER IMPACT BRACKET	Dented	195.80 FL	*195.80 FL
30	1		*BOOTLID LX 1.6 EMBLEM	Necessary	84.00 FL	*84.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,115.70	4,758.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,106.43	1,117.23
Total Parts (\$\$)	7,009.27	3,641.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	800.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	800.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO TRANSFER REAR BOOT MECHANISM	New	120.00	80.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	60.00
6	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
8	TO REMOVE AND REFIX UPHOLSTERY	New	150.00	80.00
9	TO REMOVE REVERSE SENSOR	New	100.00	50.00
10	TO REMOVE AND REFIX BOOTLID SPOILER	New	100.00	80.00
Gross Labour Cost (\$\$)			4,240.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >